Form 3160-5 (June 1090)

## UNITED STATES DEPARTMENT OF THE INTERIOR

<u>/</u> ,	PORM	APPR	OVE	D
and8	M Bure	No.	100	1-0135

BUREAU OF LAND MANAGEMENT	Expires: March 31, 1993			
SUNDRY NOTIONS	5. Lease Designation and Serial No.			
Do not use this form for proposels to della services and REPORTS ON WELLS	NM 013492			
	6. If Indian, Allottee or Tribe Name			
Use "APPLICATION FOR PERMIT—" for such proposals				
SUBMIT IN TRIPLICATE				
1. Type of Well	7. If Unit or CA, Agrocopent Designation			
Well Con P&A	West Bisti Unit			
- realize of Operator	8. Well Name and No.			
Dugan Production Corp.	West Bisti Unit 118			
Cocprione No.	9. API Well No.			
P.O. Box 420, Farmington, NM 87499 (505) 325-1821	30-045-13345			
Tip Right Mill or Survey Description)	10. Field and Pool, or Exploratory Area			
660' FSL - 660' FFL	Bisti Lower Gallup			
Sec. 20, T26N, R13W, NMPM	1. County or Parish, State			
	San Juan, NM			
CHECK APPROPRIATE BOX(s) TO INDICATE MATURE OF THE				
CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT  TYPE OF SUBMISSION	OR OTHER DATA			
TVDC OC ACTION				
Notice of Inter D) E G E V E N X Abandonment				
	Change of Plans			
Subsequent Report  JUN1 4 1993  Recompletion Plugging Back	New Construction			
	Non-Routine Fracturing			
Final Abandonme Off CON DIV Casing Repair Altering Casing	Water Shut-Off			
DIST. 3 Other	Conversion to Injection			
	Dispose Water			
13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any parties and some pertinent to this work.)*	empletion or Recompletion Report and Log form			
or all markers and zones pertinent to this work.)	roposed work. If well is directionally drilled,			
Plugged well as follows:				
Perforate Maca Manda and 20031.				
3. Spot cu. ft. Class B coment with 24 coal				
- 2488' 2488'. Displace cement to 2270'. M	esa Verde blue 22701			
5. Snot 176 cu 46 at 16521.	P. 23 LE10			
Pictured Cliffs - Fruithand alum trace	da dia. L. I			
6. Perforate below surface casing at 4001. Compart to aug.	93			
get followed by 59 cu. ft. Class B cement.	B cement with 4			
Job complete 6-4-93.				
	₩ <b>5</b> 80			
	ING. A			
	AM AE			
The first of the f	2 = 0			
The second of th	<b>z</b> -			
Plugged well as follows:  1. Run tubing and tag cement at 49131. 2. Perforate Mesa Verde at 24701. 3. Spot cu. ft. Class B cement with 2% CaCl <sub>2</sub> at 24881. Displace cement to 22701. M 24881. 4. Perforate Pictured Cliffs at 16521. 5. Spot 176 cu. ft. Class B cement with 4% gel at 1659. Displace cement to 13151. Pictured Cliffs - Fruitland plug 13151 - 16591. 6. Perforate below surface casing at 4001. Cement to surface with 161 cu. ft. Class gel followed by 59 cu. ft. Class B cement.  Job complete 6-4-93.	<u> </u>			
I toba to the time				
(This space for Federal or State office use)  Title Operations Manager	6/9/93			
Approved by	DDDAMER			
Conditions of approval, if any:				
	The same of the sa			

e 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements