

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE*
(Other instructions on reverse side)

Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.
14-20-603-5019

6. IF INDIAN, ALLOTTEE OR TRIBE NAME
Navajo

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME
Navajo Tocito

9. WELL NO.
2

10. FIELD AND POOL, OR WILDCAT
Tocito Dome

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA
Sec. 3-T26N-R18W

12. COUNTY OR PARISH
San Juan

13. STATE
N.M.

SUNDRY NOTICES AND REPORTS ON WELLS
(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☐ GAS WELL ☐ OTHER ☒ **Plug and Abandon**

2. NAME OF OPERATOR
Southern Gulf Production Company

3. ADDRESS OF OPERATOR
1801 C & I Building, Houston, Texas 77002

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.)
At surface
1980°/S & 660°/W

14. PERMIT NO.
15. ELEVATIONS (Show whether DF, RT, GR, etc.)
5695' (Gr)

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

☐
☐
☐
☐
☐

PULL OR ALTER CASING
MULTIPLE COMPLETE
ABANDON*
CHANGE PLANS

☐
☐
☒
☐
☐

SUBSEQUENT REPORT ON:

☐
☐
☐
☐
☐

WATER SHUT-OFF
FRACTURE TREATMENT
SHOOTING OR ACIDIZING
(Other)

REPAIRING WELL
ALTERING CASING
ABANDONMENT*

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

It is proposed to plug and abandon the well in the following manner.

1. Set 50' cement plug across perforations 6229'-6237'.
2. Cut off casing between 5500 and 5600' (Top of cement at 5600'). Set 50' cement plug in and out of casing stub.
3. If casing cut off below 5567' (Top of Hermosa) set 100' cement plug from 5500'-5600'.
4. Set 100' cement plug from 3800'-3900' (Top of Pochelly at 3864').
5. Set 100' cement from 2100'-2200' (Top of Tocito at 2132').
6. Set surface marker with cement at surface.

Verbal approval received on May 13, 1968.

18. I hereby certify that the foregoing is true and correct

SIGNED

[Signature]

P. E. TITLE **Petroleum Engineer**

Consultant

DATE

May 14, 1968

(This space for Federal or State office use)

APPROVED BY

TITLE

CONDITIONS OF APPROVAL, IF ANY: