Form 3160-5 (June 1990)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT



FORM APPROVED
Budget Bureau No 1004-0135
Expires: March 31, 1993

Of IIII 25 CH		5. Lease Designation and Serial No. NM 05791
SUNDRY NOTICES AND REPORTS ON WELLS 2: 03 Do not use this form for proposals to drill or to deepen of reentry to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals: 101, N.M.		6. If Indian, Allottee or Tribe Name
SUBMIT IN TRIPLICATE		7. If Unit or CA, Agreement Designation
I. Type of Well Oil X Gas Well X Well Other		
Well A Well Other 2. Name of Operator 2. Name of Operator 3. Name of Operator 4. D. Box, 1058		8. Well Name and No. Federal "M"
		9. API Well No.
3. Address and Telephone No.		1
2922 Hwy 74 Suite #309, Evergreen, CO 80439 303 674-7633 4. Location of Well (Footage, Sec., T., R., M., or Survey Description)		10. Field and Pool, or Exploratory Area Blanco Mesa Verde
1190' FSL and 1800' FWL		Blanco Mesa Verde Basin Dakota II. County or Parish, State
Sec. 3 T-27-N, R-8-W		
CUEOK APPROPRIATE POW TO WIND TO THE POWER T		San Juan New Mexico
12. CHECK APPROPRIATE BOX	(s) TO INDICATE NATURE OF NOTICE, REPOR	RT, OR OTHER DATA
TYPE OF SUBMISSION	TYPE OF ACTION	
X Notice of Intent	Abandonment	Change of Plans
	Recompletion	New Construction
Subsequent Report	Plugging Back	Non-Routine Fracturing
Final Abandonment Notice	Casing Repair Altering Casing	Water Shut-Off
and promised proces	Other	Conversion to Injection Dispose Water
		(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)
13. Describe Proposed or Completed Operations (Clearly state a	Il pertinent details, and give pertinent dates, including estimated date of starting cal depths for all markers and zones pertinent to this work.)*	any proposed work. If well is directionally drilled,
Check the integrity of 5½ csg	·	
Check Dakota Formation, see if it is commercially productive.		
08/30/91 Move in work over rig, set B.O.P., lay down 12" I.J. Tubing both zones.		
Pick up 2 3/8" Tubing for workover string, trip in hole with seal assembly for		
Model "D" Packer @ 6365', string in Packer and test Dakota, if found commercially		
productive, set Blanking Tool in Model "D", Trip in hole with retrievamatic Packer.		
set Packer below M.V. Perf. (@ 4213-4429). Test csg. across Gallup Section, if ok,		
put both zones on Production. If Dakota Zone is not commercially productive, pump 25		
sacks regular neet cement (29,50 cu. ft.) while stung into Model "D" packer (6365') pick tubing up spot 10 sacks (11.80 cu.ft.) on top of Model "D", W.O.C. 8 hours, tag		
cement, return well to single	zone completion	U.C. 8 hours, tag
comenc, return werr to single		
DOE GETAEU		
	ען אווי אווי אווי אווי אווי אווי אווי אוו	
	JUL 3 1 1991.	
•	OIL CON. DIV.)	Control of the Contro
	DIST. 3	APPROVED
4. I hereby certify that the foregoing is true and correct		
Signed State Charles	Tide Agent for L.P. Moore	Date07/24/91
(This space for Federal or State office use)		JUL 2 9 1991
Approved by	Title	Date
		T8
		AREA MANAGER
Title 18 U.S.C. Section 1001, makes it a crime for any person- ic representations as to any matter within its jurisdiction.	knowingly and willfully to make to any department or agency of the United S	ates any faise, lictitious or fraudulent statements