

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

# NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. SF 080127

## SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT --" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER-	7. Unit Agreement Name Huerfano Unit
2. Name of Operator El Paso Natural Gas Company	8. Farm or Lease Name Huerfano Unit
3. Address of Operator P. O. Box 990 Farmington, New Mexico 87401	9. Well No. 192
4. Location of Well UNIT LETTER P, 800 FEET FROM THE South LINE AND 800 FEET FROM THE East LINE, SECTION 22 TOWNSHIP 26 N RANGE 9 W NMPM.	10. Field and Pool, or Wildcat Basin Dakota
15. Elevation (Show whether DF, RT, GR, etc.) 6385 GL	12. County San Juan

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input checked="" type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Set choke in Guiberson production packer unseat on-off tool from packer.
2. Circulate 66 Bbls of Baroid packer fluid in annulus, displacing the tubing with 10 Bbls of diesel and 14 Bbls of water.
3. Connect back into packer with on-off tool.
4. Pull choke and swab well in.



18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED *Arthur J. Smith* TITLE Production Engineer DATE 13 June, 1975  
APPROVED BY *Emory Church* TITLE SUPERVISOR DIST. #3 DATE JUN 16 1975  
CONDITIONS OF APPROVAL IF ANY: