Form 3160-5 (June 1990)

UNITED STATES

FORM APPROVED

, , ,	NT OF THE INTERIOR LAND MANAGEMENT EGENTS (Expires: March 31, 1993 5. Lease Designation and Serial No.
SUNDRY NOTICES AND REPORTS ON WELLS		NMSF-078476
SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to deepen or reentry to different reservoir.		6 If Indian, Allottee or Tribe Name
Use "APPLICATION FO	R PERMIT—" for such proposals	
SUBMIT IN TRIPLICATE (1) The STON, Not		7. If Unit or CA, Agreement Designation
1 Type of Well		UNIT D
Well X Well Other		R. Well Name and No
Name of Operator BLEDSOE PETRO CORPORATION		FEDERAL E 3
3 Address and Telephone No.	214/742-5800	9 API Well No.
1717 MAIN STREET SUITE 5850 DALLAS TX 75201		10. Field and Pool, or Exploratory Area / Jose
4 Location of Well (Footage, Sec., T., R., M., or Survey Description)		BLANCO MESAVERDE Charre
/3 T.27 N. R.8 W. SEE. ID 790' FNL & 790' FEL		11. County or Parish, State
790 FNL & 790 FEL		SAN JUAN, NEW MEXICO
CHECK APPROPRIATE BOX	(s) TO INDICATE NATURE OF NOTICE, REPO	RT, OR OTHER DATA
TYPE OF SUBMISSION	TYPE OF ACTION	
X Notice of Intent	X Abandonment	Change of Plans
Π	Recompletion	New Construction
Subsequent Report	Plugging Back	Non-Routine Fracturing
Final Abandonment Notice	Casing Repair Altering Casing	Water Shut-Off
· ·······························	Other	Conversion to Injection Dispose Water
		(Note Report results of multiple completion on Well Completion or Recompletion Report and Log form)
TOP OF NACIMIENTO TOP OF OJO ALAMO TOP OF KIRTLAND TOP OF FRUITLAND TOP OF PICTURED CLIFF TOP OF LEWIS TOP OF CHACRA TOP OF CLIFF HOUSE TOP OF MENEFEE TOP OF POINT LOOKOUT TOP OT MANCOS	3108' 3909' 4661' PL	EASE SEE ATTACHED FOR PROCEDURES
14. I hereby erith that the foregoing is true and correct Signed (This space for Federal or Star office use) Approved by Conditions of approval, if any:	Title PETROLEUM ENGINEER	Date
Title 18 U.S.C. Section 1001, makes it a crime for any person or representations as to any matter within its jurisdiction.	knowingly and willfully to make to any department or agency of the United	Since any false, figtificus or fraudulent statements

*See instruction on Reverse Side

BLEDSOE PETRO CORPORATION PLUGGING PROCEDURES FEDERAL E 3

- Set CIBP @ 4611' and spot 50' of cement on top of plug
- Perf @ 3959', place cement plug from 3959' to 3859' inside and outside the casing with 100% excess cement in the annulus and an additional 50 linear feet inside the casing.
- Perf @ 2827', place cement plug from 2827' to 2727' inside and outside with 100% excess in the annulus and an additional 50 linear feet inside the casing.
- Perf @ 2302', place cement plug from 2302' to 2098' inside and outside casing with 100% excess in the annulus with and 50 linear feet inside the casing.
- 5) Perf @ 1243', place cement plug from 1243' to 1143' inside and outside casing with 100% excess in the annulus with and 50 linear feet inside the casing.
 - 6) Perf 0 227' and circulate cement to surface.