

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLICATE*
(Other instructions on reverse side)

Budget Bureau No. 1004-0135
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. <input type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER	5. LEASE DESIGNATION AND SERIAL NO. I-149-IND 7971
2. NAME OF OPERATOR Tenneco Oil Company	6. IF INDIAN, ALLOTTEE OR TRIBE NAME Navajo
3. ADDRESS OF OPERATOR P.O. Box 3249, Englewood, CO 80155	7. UNIT AGREEMENT NAME
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 1785' FNL, 1850' FEL	8. NAME OF LEASE NAME Gallegos
14. PERMIT NO.	9. WELL NO. 1
15. ELEVATIONS (Show whether BP, ST, GR, etc.) 6097' GR	10. FIELD AND POOL, OR WILDCAT Basin Dakota
	11. SEC., T., R., N., OR BLK. AND SURVEY OR AREA Sec. 29, T26N, R11W
	12. COUNTY OR PARISH San Juan
	13. STATE NM

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF	<input type="checkbox"/>	WATER SHUT-OFF	<input type="checkbox"/>
FRACTURE TREAT	<input type="checkbox"/>	FRACTURE TREATMENT	<input type="checkbox"/>
SHOOT OR ACIDIZE	<input type="checkbox"/>	SHOOTING OR ACIDIZING	<input type="checkbox"/>
REPAIR WELL	<input type="checkbox"/>	(Other) <u>Well Repair</u>	<input checked="" type="checkbox"/>
(Other)	<input type="checkbox"/>	(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)	

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and notes pertinent to this work.)*

Per your request, the referenced well did not need any casing repair after further analysis. Tenneco does not plan to do any casing repair on the Gallegos #1.

RECEIVED
BLM MAIL ROOM
87 OCT 19 AM 8:35
FARMINGTON RESOURCE AREA
FARMINGTON, NEW MEXICO

RECEIVED
OCT 23 1987
OIL CON. DIV.
DIST. 3

18. I hereby certify that the foregoing is true and correct

SIGNED

David Hiatt

TITLE Sr. Admin. Analyst

DATE 10/15/87

(This space for Federal or State office use)

APPROVED BY
CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

OCT 20 1987

ACCEPTED FOR RECORD

*See Instructions on Reverse Side

NMOCC

FARMINGTON RESOURCE AREA

BY KIL