any matter within its jurisdiction.

## UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED Budget Bureau No. 1004-0135

Expires: March 31, 1993

Do not use this form for pr	TICES AND REPORTS ON WELLS roposals to drill or to deepen or reentry to a different reservoir. CATION FOR PERMIT - " for such proposals	5. Lease Designation and Serial No.  I-149-IND-7971  6. If Indian, Allottee or Tribe Name
		7. If Unit or CA, Agreement Designation
1. Type of Well		
Oil Gas Other		8. Well Name and No.
2. Name of Operator	Attention:	Gallegos 1
Amoco Production Company	Beth Gonzalez	9. API Well No.
3. Address and Telephone No. P.O. Box 800, Denver, Colorado 8	80201 (303) 830-5651	3004521228  10. Field and Pool, or Exploratory Area
4. Location of Well (Footage, Sec., T., R., M., or S		Basin Dakota
	!	11. County or Parish, State
1785 FNL 1850 FEL	_ Sec. 29 T 26N R 11W	San Juan New Mexico
12. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA		
TYPE OF SUBMISSION	TYPE OF ACTION	
Notice of Intent  Subsequent Report  Final Abandonment Notice	Abandonment  Recompletion  Plugging Back  Casing Repair  Altering Casing  Other  (Note: Repor	Change of Plans  New Construction  Non-Routine Fracturing  Water Shut-Off  Conversion to Injection  Dispose Water  t results of multiple completion on Well Completion or a Report and Log form.
	requests permission to perform the attached proceedures for the  ase call Beth Gonzalez @ (303) 830-5206.  DECEIVE  AUG - 8 1994  OIL CON. DI  DIST. 3	RECEIVED BLM 94 JUL 28 AH IO: 17 070 FARMINGTON, NM
14. I hereby certify that the foregoing is true and considered (This space for Federal or State office use)	Business Ana	Nyst Date 07-27-1994
Approved by Conditions of approval, if any:	Title	Date
Title 18 U.S.C. Section 1001, makes it a crime for a	any person knowingly and willfully to make to any department or agency of the United States any	alse, ficticious, or traudulent statements or representations as to

\* See Instructions on Reverse Side

NMOCD

## PXA Procedures Gallegos #1

- Check location for anchors. Install if necessary. Test anchors.
- 2. MIRUSU. Blow down well. Kill if necessary with fresh water. NDWH. NUBOP.
- 3. POOH with 2 7/8" tbg. RIH with tbg and cement retainer, set retainer at 5775' and squeeze perfs at 5808' to 5830' with 42.136 cuft cement. Pull out of retainer and spot 2 sx of cement on top.
- 4. Load hole with 9ppg mud to 4800 .
- 5. Spot cement plug to 630' with 545.436 cuft cement. Run short string CBL to determine TOC. RIH with perfing gun and shoot squeeze holes where TOC is indicated on CBL. Circulate to surface and fill hole with 369.432 cuft cement.
- 6. NDBOP. Cut off casing and wellhead. Install PXA marker according to BLM or State requirements.
- 7. Turn over to John Schwartz for reclamation.
- 8. Rehabilitate location according to BLM or state requirements.

## GALLEGOS 001 17 Location — 29G— 26N—11W SINGLE dk Orig.Completion — 5/73 Last File Update — 1/89 by BCB

