



STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT
OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE

TONEY ANAYA
GOVERNOR

1000 RIO BRAZOS ROAD
AZTEC, NEW MEXICO 87410
(505) 334-6178

September 20, 1985

Mr. Ricky Broussard
Amoco Production Co.
501 Airport Dr.
Farmington, NM 87401

Re: Navajo Tribal U #14 K-16-26N-18W

Dear Mr. Broussard:

The enclosed bradenhead test on the referenced well indicates a casing failure. In order to comply with Rule 108, prevent waste and protect fresh water, you are hereby directed to initiate immediate remedial activity.

If you have any questions, please contact this office.

Your truly,

A handwritten signature in cursive script, appearing to read "Charles Gholson".

Charles Gholson
Oil & Gas Inspector

CG/dj

xc: Well File