Form approved. Form 3160-5 Budget Bureau No. 1004-0135 SUBMIT IN TRIPLICATE*
(Other instructions on re-UNITED STATES (November 1983) Expires August 31, 1985 DEPARTMENT OF THE INTERIOR (Other Interior verse side) (Formerly 9-331) 5. LEASE DESIGNATION AND SERIAL NO. BUREAU OF LAND MANAGEMENT 4-20-0603-8103 6. IF INDIAN, ALLOTTEE OR TRIBE NAME SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a differ free Use "APPLICATION FOR PERMIT—" for such proposals. <u>Na</u>vajo 7. UNIT AGREEMENT NAME WELL WELL X OTHER MAR 2 6 1987 NAME OF OPERATOR 8. FARM OR LEASE NAME CON DIV Texaco Inc Navajo Tribe AR REGIESVED P. O. BOX EE, Cortez, Co. 81321

LOCATION OF WELL (Report location clearly and in accordance with any State requirements.

At surface

AMAD O. 4. 10. PIELD AND POOL, OR WILDCAT MAR 24 1987 Tocito Dome Penn D

11. SEC., T., E., M., OR BLE. AND
SURVEY OR AREA 660' FNL & 810' FEL BUREAU OF LAND MANAGEMENT FARMINGTON RESOURCE AREA Sec 27, T26W, R28W 14. PERMIT NO. 15. ELEVATIONS (Show whether Dr. RT, OR, etc.) 5655' KB San Juan NM 16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: TEST WATER SHUT-OFF PULL OR ALTER CASING WATER SHUT-OFF REPAIRING WELL FRACTURE TREAT MULTIPLE COMPLETE FRACTURE TREATMENT ALTERING CASING SHOOT OR ACIDIZE ABANDON* SHOOTING OR ACIDIZING ABANDONMENT* REPAIR WELL CHANGE PLANS (Other) (Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.) (Other) 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)* The subject well was completed as Plugged and Abandoned, March 3, 1987. The following procedure was carried out during the plugging operations. 1) MIRUSU - TOOH w/rods & pump. Nipple up BOPS & TOOH w/tubing & A.C. 2) TIH open ended to 6266' KB. Spot 25 sxs Class B cement from 6266'-6141'. No circulation. Let cement set 2 hrs. TIH & tag cement at 6135'. 3) Started to displace hole w/9.2#/gal brine based mud. Lost circulation. Lowered tubing to 6266' KB. No cement plug. Spot another 25 sxs Class B cement plug from 6266' to 6141'. Shut down for night. 4) Lowered tubing to 6266' KB. No cement plug. TOOH w/tubing. TIN w/tubing & 7"cement retainer. Retainer stuck at 1218', worked free. TOOH w/cement retainer. 5) TIH w/tubing open ended to 6266'. Spot 50 sxs Class B cement w/3% CaCl2 and 1/4 /sak cellphane flakes from 6266'-6016'. Shut down for night. 6) TIH w/tubing & tagged cement at 5910'. Displace hole w/9.2#/gal brine based mud. 7) TOOH spotting 25 sxs Class B cement at the following depths 5445'-5330', 3725'-3600', 2066'-1941', 1675'-1550'. 8) Pulled tubing to 825'. Spot 25 sxs Class B cement from 825'-700'. returns up bradenhead & casing. Shut down for night. (cont on attached page) 18. I hereby certify that the foregoing is true and correct Mari TITLE Area Superintendent DATE 3/23/87 (This space for Federal or State office use) MAR S APPROVED BY ... TITLE CONDITIONS OF APPROVAL, IF ANY: Saleta Sitte MASUN BLM (4) Navajo Tribe JNH LAAAAK MLK ARES, Villey Approved as in plagging of the well bare. FARMINGTON NECDER 12 *See Instructions on Reverse Side Liability under bond is revaled a writi-

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any

surface restoration is completed.

- 9) TIH w/tubing. Tag cement at 1550'. TOOH w/tubing. Rig up cementers to bradenhead. Pump 100 sxs Class B cement down bradenhead. Full returns up 7" casing. Shut well in for 3 hours. TIH w/tubing to 825'. Spot 25sxs Class B cement from 825'-700' KB. 100% returns up casing. No returns up bradenhead.
- 10) Pull tubing to 150' KB. Spot 30 sxs Class B cement from 150'- surface. Shut well in for night.
- 11) Pump additional 10 sxs Calss B cement down 7" casing cut off wellhead.
- 12) Clean location and install dryhole marker. Operations complete March 3, 1987.

NOTE: Location will be seeded between July 1 and Sept 1 with the prescribed seed mix.