

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE
(Other instructions on reverse side)

Form approved.
Budget Bureau No. 42 R1424.
5. LEASE DESIGNATION AND REEL NO.
FED. NOO-C14-20-2727
6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR

3. ADDRESS OF OPERATOR
TEXACO, Inc.

P.O. Box EE, Cortez, Colo. 81321

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.
See also space 17 below.)
At surface

1980' from South line and 1980' from West line.

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

5592' DF

Navajo Tribe
7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Navajo Tribe "BF"

9. WELL NO.

2

10. FIELD AND POOL, OR WILDCAT

Tocito Dome Field

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

K-26-T26N-R18W

12. COUNTY OR PARISH

13. STATE

San Juan

N. Mex.

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

☐
☐
☐
☐
☐

PULL OR ALTER CASING

☐
☐
☐
☐
☐

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

☐
☐
☐
☐
☐

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

☐
☐
☐
☒
☐

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) *

10-26-76. MIRUSU. Spot 50 sx. cement across perms. 5700' - 6062'.

Pulled 6018' of tbg. Cut off csg. at 3100' and pulled out of hole. Tripped in hole to 3162' and set 50 sx. plug.

Pulled and layed down tbg. to 1635' and set 50 sx. plug

Pulled and layed down tbg. set 10 sx. plug at surface.

Errected hole marker and cleaned up location.

18. I hereby certify that the foregoing is true, and correct

SIGNED *A. R. Marshall*

TITLE Field Foreman

DATE 11-16-76

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

*See Instructions on Reverse Side

USGS(3) NMOCC(2) Navajo Tribe-JAS-GLE-ARM