

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil ☒ well gas ☐ well other ☐
2. NAME OF OPERATOR
Mobil Oil Corporation
3. ADDRESS OF OPERATOR
9 Greenway Plaza, Suite 2700, Hous., TX 77046
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)
AT SURFACE: 1980' FWL & 660' FSL of Sec. 9,
AT TOP PROD. INTERVAL: T-26-N, R-18-W
AT TOTAL DEPTH:

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF	<input type="checkbox"/>		<input type="checkbox"/>
FRACTURE TREAT	<input type="checkbox"/>		<input type="checkbox"/>
SHOOT OR ACIDIZE	<input type="checkbox"/>		<input type="checkbox"/>
REPAIR WELL	<input type="checkbox"/>		<input type="checkbox"/>
PULL OR ALTER CASING	<input type="checkbox"/>		<input type="checkbox"/>
MULTIPLE COMPLETE	<input type="checkbox"/>		<input type="checkbox"/>
CHANGE ZONES	<input type="checkbox"/>		<input type="checkbox"/>
ABANDON*	<input checked="" type="checkbox"/>		<input type="checkbox"/>
(other)			

5. LEASE
Navajo Contract 14-20-603-5019
6. IF INDIAN, ALLOTTEE OR TRIBE NAME
7. UNIT AGREEMENT NAME
8. FARM OR LEASE NAME
Navajo
9. WELL NO.
2
10. FIELD OR WILDCAT NAME
Tocito Dome/Penn. E
11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA
Sec. 9, T-26-N, R-18-W
12. COUNTY OR PARISH
San Juan
13. STATE
NM
14. API NO.
15. ELEVATIONS (SHOW DF, KDB, AND WD)
NA

(NOTE: Report results of multiple completion or zone change on Form 9-330.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

- 1) Kill well; pull rods, pump & tbg.
- 2) Set CIBP @ 6300', cap w/ 8x H cmt.
- 3) Run FPI, cut & pull 7" csg. (TOC @ 5175' by temp. survey 22# J 55 csg to 3400', 24# G.C csg 3400-5000', 23# J-55 csg. 5000-6497')
- 4) Load hole w/ 9.5# brine + 25x gel/100 bbl water.
- 5) Spot 200' cmt plug across 7" csg. stub (150' above & 50' below cut-off point) w/ 70' 8x C1 H.
- 6) Spot 200' cmt plug 4200-4400 w/ 80 x H cmt.
- 7) Spot 165' plug across 10-3/4" csg. shoe from 1600-1765' w/ 25x H cmt.
- 8) Spot a 50' 25x plug @ surface & erect P&A marker.
- 9) Clear location when BLM approval is rec'd.

NOTE: Plugging procedure discussed w/ Don Miller of Farmington USGS.

Subsurface Safety Valve: Manu. and Type _____

18. I hereby certify that the foregoing is true and correct.

SIGNED Virginia Howard TITLE Authorized Agent DATE September 19, 1978

(This space for Federal or State office use)

APPROVED BY _____ TITLE _____ DATE _____
CONDITIONS OF APPROVAL, IF ANY:

STATEMENT OF SURFACE RESTORATION INTENTION
ATTACHMENT TO USGS FORM 9-331, SUNDRY NOTICE OF INTENT TO ABANDON

Applicable To: Mobil Oil Corporation
Three Greenway Plaza East, Suite 800
Houston, Texas 77046

Lease Name: Navajo

Well No: 2

Location: 1980' FWL & 660' FSL, Sec. 9, T-26-N, R-18-W

This is to advise your office that surface restoration associated with the above described proposed plugging and abandonment will be conducted in accordance with applicable rules and regulations of the United States Geological Survey and the New Mexico Oil Conservation Commission; and in accordance with any existent agreement with the surface landowner, or in a manner arrived at by agreement with the surface landowner.

Such restoration work will include:

Backfilling of all pits and cellar. Levelling or contouring the location site. Clearing the location area of junk.

FORM 9-331 Dated: 9-19-78