

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIPLICATE*
(Other Instructions on reverse side)Form approved
Budget Bureau No. 42 R1424.

7. TASK DESIGNATION AND SERIAL NO.

14-20-0603-8103

8. IF INDIAN, ALLOTTEE OR TRIBE NAME

Navajo Tribe

9. FIELD OR TRAIL NAME

Navajo Tribe "AR"

10. WELL NO.

7

11. FIELD AND POOL, OR WILDPAT

Tocito Dome Penn "D"

12. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

N-27-26N-18W

13. COUNTY OR PARISH 14. STATE

San Juan

New Mex.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use APPLICATION FOR PERMIT for such proposals.)

1. NAME OF OPERATOR
TEXACO, Inc. Prod. Dept. West U.S.
2. ADDRESS OF OPERATOR
P. O. Box EE, Cortez, CO. 81321
3. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. *
See also space 17 below.)
At surface:

810' from South line and 1980' from West line.

14. PERMIT NO. 15. ELEVATIONS (Show whether DE, RT, GR, etc.)

5696' GR

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER RHEOLOGY	ENTER OR ALTER CASING
FRACURE TREAT	MULTIPLE COMPLETE
SHOOT OR ACIDIZE	ABANDON*
REPAIR WELL	CHANGE PLANS
(Other)	

SUBSEQUENT REPORT OF:

WATER SAMPLE	REPAIRING WELL
FRACURE TREATMENT	ALTERING CASING
SHOOTING OR ACIDIZING	ABANDONMENT*
(Other)	

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state: 1) pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) *

Abandonment commenced 11-13-77.

Set 60 sx cement plug across perforations. Cut 2-7/8" tubing at 3145', but tubing remained stuck. Ran free point and cut tubing at 2468'. Set 40 sx cement plug at 2468'. SI and WOC. Tagged plug at 2468', and set another cement plug (80 sx). Set 20 sx cement plug at surface. Erected dry hole marker and cleaned up location. Abandonment completed 11-16-77.

18. I hereby certify that the foregoing is true and correct

SIGNED _____

TITLE **Field Foreman**DATE **12-5-77**

(This space for Federal or State office use)

APPROVED BY _____
CONDITIONS OF APPROVAL, IF ANY:

TITLE _____

DATE _____

*See Instructions on Reverse Side

USGS(4) MOGCC(3) The Navajo Tribe-GLC-A M-THP