Form Approved.				
Budget	Bureau	No.	42-R1424	

UNITED STATES	5. LEASE
DEPARTMENT OF THE INTERIOR	NM 12028
GEOLOGICAL SURVEY	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9–331–C for such proposals.)	7. UNIT AGREEMENT NAME 8. FARM OR LEASE NAME
1. oil gas well other	Chaco Plant 9. WELL NO.
2. NAME OF OPERATOR Jerome P. McHugh	10. FIELD OR WILDCAT NAME
3. ADDRESS OF OPERATOR Box 234, Farmington, NM 87401	Undesignated - PC 11. SEC., T., R., M., OR BLK. AND SURVEY OR
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.) AT SURFACE: 850' FNL - 1510' FEL AT TOP PROD. INTERVAL: AT TOTAL DEPTH:	AREA Sec 20 T26N R12W 12. COUNTY OR PARISH 13. STATE San Juan NM 14. API NO.
 CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA 	15. ELEVATIONS (SHOW DF, KDB, AND WD) 6037!
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF: TEST WATER SHUT-OFF FRACTURE TREAT SHOOT OR ACIDIZE REPAIR WELL PULL OR ALTER CASING MULTIPLE COMPLETE CHANGE ZONES ABANDON* SUBSEQUENT REPORT OF: CHANGE ZONES ABANDON*	(NOTE: Report results of multiple completion or zone change on Form 9–330.)
(other) 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state including estimated date of starting any proposed work. If well is a measured and true vertical depths for all markers and zones pertined.	directionally drilled, give subsurface locations and
Plan to plug and abandon as follows:	;
1. Plan to pull 1-1/4" tbg	
2. Plan to spot cement plug from 1150 - 104	10'
3. Spot surface plug from surface to 200'	CH IT IS
4. Cut off csg below ground level	
5. Clean up location	Set @
Subsurface Safety Valve: Manu. and Type	Set @ CON. 3
18. I hereby certify that the foregoing is true and correct	
SIGNED THE Agent TITLE Agent Thomas A Dugan Thomas A State of	
(This space for Federal or State of	mice use/