

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLICATE*
(Other instructions on re-
verse side)

Budget Bureau No. 1001
Expires August 31, 1985

5. LEASE DESIGNATION AND SERIAL NO.

N00-C-14-20-5432

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

Navajo Tribe

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Navajo Tribe "BU"

9. WELL NO.

2

10. FIELD AND POOL, OR WILDCAT

Tocito Dome

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

Sec 34, T26N, R18W

12. COUNTY OR PARISH

13. STATE

San Juan

New Mexico

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR

Texaco Inc.

3. ADDRESS OF OPERATOR

P.O. Box EE, Cortez, Colo. 81321

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface

NW $\frac{1}{4}$ -NE $\frac{1}{4}$ Sec 34
660' FNL & 1980' FEL, Sec 34

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

5625' KB

16.

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETION

ABANDON*

CHANGE PLANS

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

SUBSEQUENT REPORT OF:

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Texaco Inc. proposes to perforate and acidize the Navajo
Tribe "BU" 2 as follows:

- 1.) MIRUSU
- 2.) TOOH w/downhole equipment. Nipple up BOP's
- 3.) Perforate 6314'-6322' w/4 jspf.
- 4.) Acidize 6314'-6322' w/1200 gallons 15% HcL.
- 5.) Acidize existing perforations 6238-6294 w/1200 gallons 15% HcL.
- 6.) Recover load.
- 7.) Return well to production.

APPROVED

OCT 16 1987

OCT 15 1987

AREA MANAGER

18. I hereby certify that the foregoing is true and correct

SIGNED

Alan A. Klever

TITLE Area Superintendent

DATE 10/2/87

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

BLM / (4) UOGCC (3) Navajo Tribe - Mobil Oil - JNH - LAA - AAK

*See Instructions on Reverse Side