

**SUNDRY NOTICES AND REPORTS ON WELLS**

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER	<b>RECEIVED</b> <b>AUG 30 1985</b> BUREAU OF LAND MANAGEMENT FARMINGTON RESOURCE AREA
2. NAME OF OPERATOR DUGAN PRODUCTION CORP.	
3. ADDRESS OF OPERATOR P O Box 208, Farmington, NM 87499	
4. LOCATION OF WELL (Report location clearly and in accordance with BLM Form 3160-5, Rev. 1-83) See also space 17 below.) At surface 1500' FSL - 790' FWL	
14. PERMIT NO.	15. ELEVATIONS (Show whether DF, RT, CR, etc.) 6174' GL

5. LEASE DESIGNATION AND SERIAL NO. NM 61	
6. IF INDIAN, ALLOTTEE OR TRIBE NAME	
7. UNIT AGREEMENT NAME	
8. FARM OR LEASE NAME Rachel	
9. WELL NO. 1	
10. FIELD AND POOL, OR WILDCAT WAW Fruitland PC	
11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 34, T26N, R12W, NMPM	
12. COUNTY OR PARISH San Juan	13. STATE NM

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF	PULL OR ALTER CASING
FRACTURE TREAT	MULTIPLE COMPLETE
SHOOT OR ACIDIZE	ABANDON*
REPAIR WELL	CHANGE PLANS
(Other)	

SUBSEQUENT REPORT OF:

WATER SHUT-OFF	REPAIRING WELL
FRACTURE TREATMENT	ALTERING CASING
SHOOTING OR ACIDIZING	ABANDONMENT*
(Other)	

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

Request permission to plug and abandon subject well as follows:

- 1) Plan to fill 2-7/8" OD, 6.5#, J-55, 8 Rd EUE tubing for casing from P.B.T.D. 1220' to surface using 34 sx (40 cf) class "B" neat cement.
- 2) Plan to install permanent dry hole monument.
- 3) Plan to fill all pits.
- 4) Plan to clean well location of all equipment, pipe, junk and trash.
- 5) Plan to restore surface.
- 6) Plan to cut off tie-downs.

18. I hereby certify that the foregoing is true and correct

SIGNED Sherman E. Dugan

TITLE Geologist

DATE 8-28-85

(This space for Federal or State office use)

APPROVED BY \_\_\_\_\_  
CONDITIONS OF APPROVAL, IF ANY:

TITLE \_\_\_\_\_

\*See Instructions on Reverse Side

NMOCC

