

1 Southland Royalty BUREAU OF LAND MANAGEMENT

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☐ GAS WELL ☒ OTHER

2. NAME OF OPERATOR
DUGAN PRODUCTION CORP.

3. ADDRESS OF OPERATOR
P O Box 208, Farmington, NM 87499

4. LOCATION OF WELL (Report location clearly and in accordance with BUREAU OF LAND MANAGEMENT
See also space 17 below.)
At surface
FARMINGTON RESOURCE AREA

1450' FSL - 1850' FEL

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

6057' GL

5. LEASE DESIGNATION AND SERIAL NO.

NM 0558240

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

County Seat

9. WELL NO.

2

10. FIELD AND POOL, OR WILDCAT

WAW Fruitland PC

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

Sec. 21, T26N, R12W, NMMP

12. COUNTY OR PARISH 13. STATE

San Juan

NM

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

PULL OR ALTER CASING

FRACTURE TREAT

MULTIPLE COMPLETE

SHOOT OR ACIDIZE

ABANDON*

REPAIR WELL

CHANGE PLANS

(Other)

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

REPAIRING WELL

FRACTURE TREATMENT

ALTERING CASING

SHOOTING OR ACIDIZING

ABANDONMENT*

(Other)

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Request permission to plug and abandon subject well as follows:

- 1) Plan to fill 2-7/8" OD, 6.5#, J-55, 8 Rd, EUE tubing for casing from P.B.T.D. 1180' to surface using 32 sx (38 cf) of class "B" neat cement.
*Place 6sx (7ft³) of cement down back side of 2 7/8" casing
- 2) Plan to install permanent dry hole monument.
- 3) Plan to fill all pits.
- 4) Plan to clean well location of all equipment, pipe, junk and trash.
- 5) Plan to restore surface.
- 6) Plan to cut off tie-downs.

18. I hereby certify that the foregoing is true and correct

SIGNED

Sherman E. Dugan
Sherman E. Dugan

TITLE

Geologist

(This space for Federal or State office use)

APPROVED BY

TITLE

CONDITIONS OF APPROVAL, IF ANY:

APPROVED

DATE

8-28-85

AS AMENDED

SEP 04 1985

John Skellern
AREA MANAGER
FARMINGTON RESOURCE AREA

*See Instructions on Reverse Side

NMOCC