

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPPLICATE*
(Other instructions on re-
verse side)

Budget Bureau No. 1004-0135
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER		7. UNIT AGREEMENT NAME	
2. NAME OF OPERATOR <i>Jerome McHugh</i>		8. FARM OR LEASE NAME <i>Chaco, N.M.</i>	
3. ADDRESS OF OPERATOR P O Box 809, Farmington, NM 87499		9. WELL NO. 8	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 1100' FSL - 1710' FEL		10. FIELD AND POOL, OR WILDCAT WAW - Fruitland <i>pc</i>	
14. PERMIT NO.		15. ELEVATIONS (Show whether DF, ST, GR, etc.) 6087' GR	
		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec, 25, T26N, R12W	
		12. COUNTY OR PARISH San Juan	
		13. STATE NM	

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF <input type="checkbox"/>	PULL OR ALTER CASING <input type="checkbox"/>	WATER SHUT-OFF <input type="checkbox"/>	REPAIRING WELL <input type="checkbox"/>
FRACTURE TREAT <input type="checkbox"/>	MULTIPLE COMPLETE <input type="checkbox"/>	FRACTURE TREATMENT <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
SHOOT OR ACIDIZE <input type="checkbox"/>	ABANDON* <input type="checkbox"/>	SHOOTING OR ACIDIZING <input type="checkbox"/>	ABANDONMENT* <input checked="" type="checkbox"/>
REPAIR WELL <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	(Other) P & A <input type="checkbox"/>	
(Other) <input type="checkbox"/>		(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)	

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

6-21-91

Plugged and abandoned well as follows:

Rigged up on 2-7/8" casing and pumped 2 bbls. water.

Formation open.

Pumped 40 sx of Class "B" cement to fill casing from TD to surface

(47 cu.ft.) Casing pressure was 54 psi before cementing. Pumped at 75 psi.

SI well at 9:15 am, 6-21-91, and allowed time to cure.

6-25-91

Cut off well head and surface casing 4' below ground level and installed dry hole marker.

Plan to clean location and restore in accordance with instructions from the surface management agency.

RECEIVED

JUL 09 1991

OIL CON. DIV.
DIST. 3

18. I hereby certify that the foregoing is true and correct

SIGNED *Fran Perrin*

TITLE Admin. Asst.

DATE 6-27-91

(This space for Federal or State office use)

APPROVED BY
CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

*See Instructions on Reverse Side