

DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER		6. LEASE DESIGNATION AND SERIAL NO. NM 0559974
2. NAME OF OPERATOR Kirby Exploration Company		7. IF INDIAN, ALLOTTEE OR TRIBE NAME
3. ADDRESS OF OPERATOR P.O. Box 1745, Houston, Texas 77001		8. UNIT AGREEMENT NAME
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface		9. FARM OR LEASE NAME Armour Federal
14. PERMIT NO.		10. WELL NO. 1
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 6187 GL		11. FIELD AND POOL, OR WILDCAT WAW Pictured Cliff Ext.
		12. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec 4, T26N, R13W
		13. COUNTY OR PARISH San Juan
		14. STATE New Mexico

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF	<input type="checkbox"/>	WATER SHUT-OFF	<input type="checkbox"/>
FRACTURE TREAT	<input type="checkbox"/>	FRACTURE TREATMENT	<input type="checkbox"/>
SHOOT OR ACIDIZE	<input type="checkbox"/>	SHOOTING OR ACIDIZING	<input type="checkbox"/>
REPAIR WELL	<input type="checkbox"/>	(Other)	<input type="checkbox"/>
(Other)	<input type="checkbox"/>		
PULL OR ALTER CASING	<input type="checkbox"/>	REPAIRING WELL	<input type="checkbox"/>
MULTIPLE COMPLETE	<input type="checkbox"/>	ALTERING CASING	<input type="checkbox"/>
ABANDON*	<input type="checkbox"/>	ABANDONMENT*	<input checked="" type="checkbox"/>
CHANGE PLANS	<input type="checkbox"/>		

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

Stuck drill pipe at 792 feet. Attempts to recover unsuccessful. Back off top of drill collars at 672 feet. Could not get wash pipe to top of collars. Spotted 25 sacks cement plug from 522 feet - 672 feet. Set 30 sacks cement plug from 30 feet - 148 feet. Set 5 sacks in top of surface. Cut surface pipe off 3 feet below ground level. Drill hole marker will not be installed. Hole junked and plugged and abandoned at 10:00 a.m. 5-30-76. Skid rig 10 feet north to drill Armour Federal #1-X.



MAY 31 1976  
U. S. GEOLOGICAL SURVEY  
WASHINGTON

18. I hereby certify that the foregoing is true and correct

SIGNED Jack D. Cook TITLE Agent DATE 6-1-76

(This space for Federal or State office use)

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE \_\_\_\_\_

CONDITIONS OF APPROVAL, IF ANY:

\*See Instructions on Reverse Side