(May 1963)		UNITED STATE		SUBMIT IN TRIPLIC	on re-	Form approved, Budget Bureau No. 4
		MENT OF THE		verse side)	5. 1	LEASE DESIGNATION AND SE
-		GEOLOGICAL SU	RVEY			NM 0557296-A IF INDIAN, ALLOTTEE OR TEI
		TICES AND REP				
(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals.)						
i.					7.	UNIT AGREEMENT NAME
OIL GAS OTHER P&A						
2. NAME OF OPERATOR						FARM OR LEASE NAME
Jerome P. McHugh						Chaco Plant -
3. ADDRESS OF OPERATOR Box 234. Farmington, NM 87401					•.	27
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.					10.	FIELD AND POOL, OR WILDO
See also space 17 below.) At surface						NIPP-PC Extension
	940	' FSL - 810' FE	L		11.	SEC., T., R., M., OR BLK. AND SURVEY OR AREA
						Sec 27, T26N, R1
14. PERMIT NO.		15. ELEVATIONS (Show		GR, etc.)		1
			248' GR			
16.	Check A	ppropriate Box To I	ndicate Natu	ire of Notice, Report,	, or Other	Data : : : : : : : : : : : : : : : : : :
	NOTICE OF INTE	NTION TO:		8	UBSEQUENT	REPORT OF
TEST WATER SHI	T-OFF	PULL OR ALTER CASING		WATER SHUT-OFF		REPAIRING WELL
FRACTURE TREAT		MULTIPLE COMPLETE		FRACTURE TREATMENT		ALTERING CASING
SHOOT OR ACIDIZ	B	ABANDON*		SHOOTING OR ACIDIZIN	G	ABANDONMENT* = -
REPAIR WELL		CHANGE PLANS		(Other) (Nore: Report	results of m	ultiple completion on Well
(Other)		(0)	-13			Report and Log form.)
proposed work. nent to this wor	If well is direct ·k_)*	ionally drilled, give subs	surface locations		vertical dep	
This well	. Was plugge	ed and abandone	ed in the	following manne	vertical dep	
This well	. was plugge	ed and abandone	ed in the	following manne	vertical dep	
This well	. was plugge	ed and abandone	ed in the	following manne		CE 1984
This well	Spotted 15 Spotted 20 Spotted 20	ed and abandone -sk cement plu -sk cement plu -sk cement plu	ed in the ag TD to 1 ag 320-180	following manne		GEINEDO DEC 191984 DEC 191984 DIST. 3
This well 1.	Spotted 15 Spotted 20 Spotted 20	ed and abandone -sk cement plus	ed in the ag TD to 1 ag 320-180	following manne		GEINEDO DEC 191984 DEC 191984 DIST. 3
This well 2.	Spotted 20 Spotted 15 Spotted 2- Cut off 5-	ed and abandone -sk cement plu -sk cement plu -sk cement plu	ed in the ng TD to 1 ng 320-180 g in surfa	following manners and true		DEC 19 1984 IL CON. DIV. IL COST. 3
This well 1. 2. 3.	Spotted 20 Spotted 15 Spotted 2- Cut off 5-	ed and abandone O-sk cement plu S-sk cement plu -sk cement plu -sk cement plu -sk cement plu -l/2" casing 4	ed in the ng TD to 1 ng 320-180 g in surfa	following manners and true		DEC 19 1984 DEC 18 1891
This well 1. 2. 3.	Spotted 20 Spotted 15 Spotted 2- Cut off 5-	ed and abandone O-sk cement plu S-sk cement plu -sk cement plu -sk cement plu -sk cement plu -l/2" casing 4	ed in the ng TD to 1 ng 320-180 g in surfa	following manners and true	PRINCE OF ASSESSED.	DEC 191984 DEC 1919884 DEC 191
This well 1. 2. 3.	was plugged Spotted 20 Spotted 15 Spotted 2-Cut off 5-Cleaned up	ed and abandone O-sk cement plus S-sk cement plus -sk cement plus -l/2" casing 4" o location and	ed in the ng TD to 1 ng 320-180 g in surfa	following manners and true		DEC 191984 DEC 1919884 DEC 191
This well 1. 2. 3.	was plugged Spotted 20 Spotted 15 Spotted 2-Cut off 5-Cleaned up	ed and abandone O-sk cement plus S-sk cement plus -sk cement plus -l/2" casing 4" o location and	ed in the ag TD to 1 ag 320-180 g in surfate below grandoned	following manners and true following manners ll90' ace casing cound level d well.	PE O	DEC 181891 MEDIST. 3 PPROVED AREA MANAGE.
This well 1. 2. 3. 4. 5.	was plugged Spotted 20 Spotted 15 Spotted 2-Cut off 5-Cleaned up	ed and abandone O-sk cement plus S-sk cement plus -sk cement plus -l/2" casing 4" o location and	ed in the ag TD to 1 ag 320-180 g in surfate below grandoned	following manners and true	PE O	DEC 191984 DEC 1919884 DEC 191
This well 1. 2. 3. 4. 5.	was plugged Spotted 20 Spotted 15 Spotted 2-Cut off 5-Cleaned up	ed and abandone O-sk cement plus S-sk cement plus -sk cement plus -l/2" casing 4" o location and	ed in the ag TD to 1 ag 320-180 g in surfa	following manners and true following manners ll90' ace casing cound level d well.	PE O	DEC 181081 MEDIST. 3 MEDIST. 4
This well 1. 2. 3. 4. 5. Thereby certify to SIGNED	was plugged Spotted 20 Spotted 15 Spotted 2-Cut off 5-Cleaned up	ed and abandone O-sk cement plus S-sk cement plus -sk cement plus -l/2" casing 4" o location and	ed in the ag TD to 1 ag 320-180 g in surfate below grandoned	following manners and true following manners ll90' ace casing cound level d well.	PE O	PPROVED DEC 18 1891 MENDER DEC 18 1891 MARIEA MANY GET DATE 8-2-77
This well 1. 2. 3. 4. 5. In thereby certify the signed for it is space for it is approved by the signed approved by the signed for it is approximately approved by the signed for it is approximately ap	was plugged Spotted 20 Spotted 15 Spotted 2-Cut off 5-Cleaned up	ed and abandone O-sk cement plus S-sk cement plus -1/2" casing 4" D location and	ed in the ag TD to 1 ag 320-180 g in surfa	following manners and true following manners ll90' ace casing cound level d well.	PE O	DEC 181081 MEDIST. 3 MEDIST. 4
This well 1. 2. 3. 4. 5. In thereby certify the signed for it is space for it is approved by the signed approved by the signed for it is approximately approved by the signed for it is approximately ap	was plugged Spotted 20 Spotted 15 Spotted 2-Cut off 5-Cleaned up	ed and abandone O-sk cement plus S-sk cement plus -1/2" casing 4" D location and	ed in the ag TD to 1 ag 320-180 g in surfate below grandoned	following manners and true following manners ll90' ace casing cound level d well.	PE O	PPROVED DEC 18 1891 MENDER DEC 18 1891 MARIEA MANY GET DATE 8-2-77