

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

(Other instructions on reverse side)

Expires August 31, 1983
5. LEASE DESIGNATION AND SERIAL NO.

14-20-603-5019

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

Navajo

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Navajo

9. WELL NO.

#3

10. FIELD AND POOL, OR WILDCAT

Tocito Dome Penn D

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

Sec 9, T26N, R18W

12. COUNTY OR PARISH

San Juan

13. STATE

N. Mex.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR
Mobil Oil Corporation

3. ADDRESS OF OPERATOR
P.O. Drawer G, Cortez, Co. 81321

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.)
At surface

RECEIVED

JUN 10 1987

1050' FNL, 1845' FWL

14. PERMIT NO.

15. ELEVATIONS (Show whether DE, BT, CS, etc.)

GL: 5751'

BUREAU OF LAND MANAGEMENT
FARMINGTON RESOURCE AREA

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF

PULL OR ALTER CASING

WATER SHUT-OFF

REPAIRING WELL

FRACTURE TREAT

MULTIPLE COMPLETE

FRACTURE TREATMENT

ALTERING CASING

SHOOT OR ACIDIZE

ABANDON*

SHOOTING OR ACIDIZING

ABANDONMENT*

REPAIR WELL

CHANGE PLANS

(Other)

(Other)

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

5-19-87 MIRU.

5-20-87 Bled well down. Attempted to kill well w/ lease wtr. Killed well with 80 bbls. brine wtr. NU BOP's. POOH w/ 94 jts 2-3/8" tbg and submersible pumping equip.

5-21-87 Killed well w/ brine wtr. RIH w/ bit and csq scraper. Tagged bottom @ 6463'. POOH. RIH and set CIBP @ 6364'. Capped plug w/ 50' cement. Circulated hole full of 9.5" gel mud. Pulled tbg tail to 5550' and spotted 25 sx cement across Hermosa fm. POOH. RIH w/ 4" csq gun. Gun would not go thru mud. RIH w/ tbg to 3827' and circ. mud out of hole.

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

Approved as to plugging of the well core. Liability under bond is retained until surface restoration is completed.

*See Instructions on Reverse Side

APPROVED

DATE

6-8-87

JUN 12 1987

DATE

for AREA MANAGER
FARMINGTON RESOURCE AREA

JUN 15 1987

OIL CON. DIV.

NMOCG

Navajo #3 P & A

- 5-22-87 PDDH w/ tbq. Perf. 3825/27' w/ 4 JPF. RIH w/ 5 1/2" cement retainer on tbq and set @ 3717'. Squeezed perfs 3825/27' w/ 300 sx Class 'B' cement. Spotted 5 sx cement on top of retainer. With tbq tail @ 3600'. circ hole full of 9.5* gel mud. PDDH. RIH w/ 4" casing gun and perf. 2846/48' w/ 4 JPF. RIH w/ 5 1/2" cement retainer on 2-3/8" tbq. Set retainer @ 2735' and squeezed perfs 2846/48' w/ 900 sx Class 'B' cement. Cement circ to surface. Spotted 5 sx cement on top of retainer. Pumped 9.5* gel mud from 2635' to surface. Pulled up to 1675' and spotted 100' cement plug to 1575'. Pulled up to 875' and spotted 100' plug to 775'. Pulled up to 50' and spotted cement plug to surface.
- 5-23-87 Dug out around wellhead. Cut off 8 5/8" casing and wellhead. and 5 1/2" csq. Welded on plate and set dry hole marker.
- 5-26-87 RDMD.

Surface restoration work as per our Sundry dated 5-28-87 has been started. An additional Sundry will be submitted on completion of this work.