

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLICATE*
(Other instructions on re-
verse side)

Form approved.
Budget Bureau No. 1004-0135
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☐ GAS WELL ☒ OTHER ☐

2. NAME OF OPERATOR
Texaco Inc.

3. ADDRESS OF OPERATOR
P. O. Box EE, Cortez, CO. 81321

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.
See also space 17 below.)
At surface

1190' FSL 790' FWL

14. PERMIT NO.

15. ELEVATIONS (Show whether in **RECEIVED**
MAR 02 1987
BUREAU OF LAND MANAGEMENT
FARMINGTON RESOURCE AREA
6130 GR

5. LEASE DESIGNATION AND SERIAL NO.
NM 0560223

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME
Dome Frew Federal

9. WELL NO.
7

10. FIELD AND POOL, OR WILDCAT
WAW-Pictured Cliffs

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA
Sec. 19, T26N, R12W

12. COUNTY OR PARISH
San Juan

13. STATE
New Mexico

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF <input type="checkbox"/>	PULL OR ALTER CASING <input type="checkbox"/>	WATER SHUT-OFF <input type="checkbox"/>	REPAIRING WELL <input type="checkbox"/>
FRACTURE TREAT <input type="checkbox"/>	MULTIPLE COMPLETION <input type="checkbox"/>	FRACTURE TREATMENT <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
SHOOT OR ACIDIZE <input type="checkbox"/>	ABANDON* <input type="checkbox"/>	SHOOTING OR ACIDIZING <input type="checkbox"/>	ABANDONMENT* <input checked="" type="checkbox"/>
REPAIR WELL <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	(Other) <input type="checkbox"/>	(Other) <input type="checkbox"/>

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

The subject well was completed as Plugged and Abandoned, February 17, 1987.
The following procedure was carried out during plugging operations:

- 1) Rig up cementers to 2 7/8" casing.
- 2) Pump 50 sx Class 'B' cement down 2 7/8" csg. Displaced 31 sx out perfs at 680'-692' and left 19 sx cement in tubing. Top of cement at surface.
- 3) Pump 50 sx class 'B' cement between 7" surface and 2 7/8" production casing.
- 4) Cut off wellhead 3' below G.L.
- 5) Clean location and install dry hole marker.

NOTE: Location will be seeded between July 1, and Sept. 1 with the prescribed seed mix.

Approved as to plugging of the well. Liability under bond to restore and surface restoration is completed.

18. I hereby certify that the foregoing is true and correct

SIGNED Alan G. Kleur

TITLE AREA SUPERINTENDENT

DATE 2/18/87

(This space for Federal or State office use)

APPROVED BY _____
CONDITIONS OF APPROVAL, IF ANY:

TITLE _____

DATE MAR 05 1987

NMOGCC (3) JNH-LAA-AAK

*See Instructions on Reverse Side

NMOCC