

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

FORM APPROVED
OMB No. 1004-0135
Expires November 30, 2000

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or reenter an abandoned well. Use Form 3160-3 (APD) for such proposals.

SUBMIT IN TRIPLICATE - Other instructions on reverse side

| | | |
|--|--|---|
| 1. Type of Well <input type="checkbox"/> Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other | | 5. Lease Serial No. NM-22046 |
| 2. Name of Operator Pendragon Energy Partners c/o Walsh Engineering | | 6. If Indian, Allottee or Tribe Name |
| 3a. Address 7415 E. Main, Farmington, NM, 87402 | 3b. Phone No. (include area code) 505-327-4892 | 7. If Unit or CA/Agreement, Name and/or No. |
| 4. Location of Well (Footage, Sec., T., R., M., or Survey Description) 800' FSL and 800' FEL, Sec. 7, T26N, R12W | | 8. Well Name and No. Lansdale Federal #1 |
| | | 9. API Well No. 30-045-22787 |
| | | 10. Field and Pool, or Exploratory Area WAW Fruitland Sand PC & Farm. |
| | | 11. County or Parish, State San Juan |

12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

| TYPE OF SUBMISSION | TYPE OF ACTION | | | |
|--|---|--|--|---|
| <input checked="" type="checkbox"/> Notice of Intent | <input type="checkbox"/> Acidize | <input type="checkbox"/> Deepen | <input type="checkbox"/> Production (Start/Resume) | <input type="checkbox"/> Water Shut-Off |
| <input type="checkbox"/> Subsequent Report | <input type="checkbox"/> Alter Casing | <input type="checkbox"/> Fracture Treat | <input type="checkbox"/> Reclamation | <input type="checkbox"/> Well Integrity |
| <input type="checkbox"/> Final Abandonment Notice | <input type="checkbox"/> Casing Repair | <input type="checkbox"/> New Construction | <input type="checkbox"/> Recomplete | <input type="checkbox"/> Other |
| | <input type="checkbox"/> Change Plans | <input checked="" type="checkbox"/> Plug and Abandon | <input type="checkbox"/> Temporarily Abandon | |
| | <input type="checkbox"/> Convert to Injection | <input type="checkbox"/> Plug Back | <input type="checkbox"/> Water Disposal | |

13. Describe Proposed or Completed Operations (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration there. If the proposal is to deepen directionally or recomple horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zone. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed or Testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)

Pendragon Energy Partners proposes to plug and abandon this well according to the attached procedure.



| | |
|---|------------------------------|
| 14. I hereby certify that the foregoing is true and correct | |
| Name (Printed/Typed) Paul C. Thompson, P.E. | Title Agent |
| Signature <i>Paul C. Thompson</i> | Date June 11, 2001 |

THIS SPACE FOR FEDERAL OR STATE USE

| | | |
|---|--------|------|
| Approved by | Title | Date |
| Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon. | Office | |

Title 18 U.S.C. Section 1001, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

(Instructions on reverse)

Walsh Engineering and Production

**P & A Procedure for
Pendragon Energy Partners
Lansdale Federal #1**

Location: SE/4 Sec 7 T26N R12W
San Juan County, NM


Date: June 11, 2001

Field: Farmington / Pictured Cliffs
Surface: Navajo
Minerals: BLM NM 16470

Elev: GL 5906'
2-7/8" @ 1213'
PBSD 1135'

Procedure:

1. MOL and RU completion rig. Hold safety meeting.
2. NU 2-3/8" relief line. Blow well down and kill with water if necessary.
3. Remove 2-7/8" tubing head.
4. Connect cement truck directly to 2-7/8" tubing and fill tubing with 40 sx (47 cu.ft.) of Cl "H" cement with 1/4#/sk celloflake. Drop 60 ball sealers in the first 10 sx of cement. Pump cement until tubing stands full.
7. Cut off wellhead and install dryhole marker. Reclaim location as per BLM specifications.



Paul C. Thompson, P.E.

LANSDALE FEDERAL #1
PENDRAGON ENERGY PARTNERS.

CURRENT STATUS

P&A STATUS.

