Submit 3 Copies

to Appropriate

State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revised 1-1-89

District Office

 \mathbf{C} DISTRICT I

SUNDRY NOTICES AND REPORTS ON WELLS

P.O. Box 2088 P.O. Box 1980, Hobbs, NM 88240

DISTRICT II

P.O. Drawer DD, Artesia, NM 88210

DISTRICT III

OTHER:

1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERV	ATION	DIA	VISIO	\
-------------	-------	-----	-------	---

Santa Fe, New Mexico 87504-2088

30-0	45-	227	790

WELL API NO.

5. Indicate Type of Lease

STATE FEE 6. State Oil & Gas Lease No.

E-3148-7

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A			7. Lease Name or Unit Agreement Name						
ļ	DIFFERE	NT RESERV	DIR. USE "APP	PLICATION FOR PI	ERMIT"	o, 10000		•	
		(FORM C-10)) FOR SUCH	PROPOSALS.)	,。 。 。)[E][N	15 Ahaco	Wash	
I. Type of Well OIL WELL		GAS WELL	x	OTHER:	SEP	1 5 19			
2. Name of Operator		-			@00 a		8. Well No.		
	al Resour	rces, Inc.			<u> </u>	OM to	Propame or W	1	
3. Address of Operator					100		Pool name or W	ildcat	
P.O. E	3ox 2810	, Farming	ton, New M	exico 87499	וועצו	क्षार श	WAW	Fruitland PC	
4. Well Location									
Unit Letter	0	:790	Feet from the	South	Line and	1850	Feet from	The East	Line
Section	32		Township		ange 12W	-	МРМ	San Juan	County
			10. E	levation (Show 6102' G	whether DF, RKI	B, RT, GR, et	c.)		Contract of
11.	CI	ack Ann	ropriete D			T-4' D			
				ox to Indicate	e Nature of I		-		
NOTI	CE OF	INTEN	TION TO	•		SUBS	EQUENT I	REPORT OF:	
PERFORM REMEDIA	LWORK	PI	UG AND ABAI	NDON X	REMEDIAL WO			ALTERING CASI	
TEMPORARILY ABAN	NDON [C	HANGE PLANS		COMMENCE	DRILLING OF	PNS.	PLUG AND ABAN	IDONMENT
PULL OR ALTER CA	SING [CASING TEST	T AND CEME	NT JOB		

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

OTHER:

Central Resources, Inc. plans to plug and abandon the subject well as follows:

- 1) Plug will be set from the bottom perforation (1086') to the surface (35.3 cuft) by mixing and pumping 32 sks (36.8 cuft) of Class B neat cement.
- 2) After cement has set up, tag top and refill hole, if necessary.
- 3) Cut off wellhead and install a regulation dry hole marker.
- 4) Rehabilitate location as per NMOCD regulations.

I hearby certify that the information above is true and complete to the best of my kn	owledge an	d belief.		
SIGNATURE ALWELL THE SIGNATURE	TITLE	Production Engineer	DATE	9/1/98
TYPE OR PRINT NAME Gregory E. McIntosh			TELEPHONE NO.	(505)326-3325
(This space for State Use) ORIGINAL SIGNED BY CHARLIE T. PERFIN APPROVED BY	OI TITLE	EPUTY OIL & GAS INSPECTOR, DIST.	. #3 S	P 1.5 1998