

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLICATE*
(Other instructions on reverse side)

Budget Bureau No. 1004-0135
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. ☒ OIL WELL ☐ GAS WELL ☐ OTHER

2. NAME OF OPERATOR
Texaco Inc.

3. ADDRESS OF OPERATOR
P. O. Box EE, Cortez, CO. 81321

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface
2310' FSL, 330' FEL

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)
6051' GR

5. LEASE DESIGNATION AND SERIAL NO.
14-20-603-2085

6. IF INDIAN, ALLOTTEE OR TRIBE NAME
Navajo

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME
Dome Old Trading Post

9. WELL NO.
3

10. FIELD AND POOL, OR WILDCAT
Bisti-Lower Gallup

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA
Sec. 9, T26N, R14W

12. COUNTY OR PARISH
San Juan

13. STATE
New Mexico

18. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF	<input type="checkbox"/>	PULL OR ALTER CASING	<input type="checkbox"/>	WATER SHUT-OFF	<input type="checkbox"/>	REPAIRING WELL	<input type="checkbox"/>
FRACTURE TREAT	<input type="checkbox"/>	MULTIPLE COMPLETE	<input type="checkbox"/>	FRACTURE TREATMENT	<input type="checkbox"/>	ALTERING CAS NO	<input type="checkbox"/>
SHOOT OR ACIDIZE	<input type="checkbox"/>	ABANDON*	<input type="checkbox"/>	SHOOTING OR ACIDIZING	<input type="checkbox"/>	ABANDONMENT*	<input checked="" type="checkbox"/>
REPAIR WELL	<input type="checkbox"/>	CHANGE PLANS	<input type="checkbox"/>	(Other)	<input type="checkbox"/>		
(Other)	<input type="checkbox"/>						

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

The subject well completed as Plugged and Abandoned, February 17, 1987.
The following procedure was carried out during plugging operations:

- 1) MIRUSU-Cut off 2 3/8" tubing at 4650' and displace hole with 9.2#/Gal. Brine Based Mud.
- 2) Spot 25 sx class B cement plug from 4650' to 4323'.
- 3) Shot 4-way squeeze, perf at 3810'. Spot 30 sx class B cement plug from 3810' to 3700' and squeezing 20 sx outside casing.
- 4) Shot 4-way squeeze perf at 1960'. Set retainer at 1132' and squeeze with 230 sx class B cement.
- 5) Spot 25 sx class B cement plug from 275' to surface.
- 6) Pump 65 sx class B cement down braidenhead.
- 7) Cut off wellhead 3' below G.L.
- 8) Clean location and install dry hole marker.

NOTE: Location will be seeded between July 1, and Sept. 1 with the prescribed seed mix.

Approved by
Licensed
Surface Reclamation

18. I hereby certify that the foregoing is true and correct

SIGNED Alan C. Kleen

TITLE AREA SUPT.

(This space for Federal or State office use)

APPROVED BY
CONDITIONS OF APPROVAL, IF ANY:

TITLE

~~XXXXXXXXXX~~ - Navajo Tribe-JNH-LAA-AAK
BLM (4)

*See Instructions on Reverse Side

APPROVED
DATE 2/19/87

DATE FEB 22 1987

AREA MANAGER
FARMINGTON RESOURCE AREA