Form 9-331 (May 1963)	UNITED STATES DEPARTMENT OF THE INTE GEOLOGICAL SURVEY	SUBMIT IN TRIPLICATE (Other instructions on tweether)	5. LEASE DESIGNATION AND SERIAL NO. SF 978937
S (Do not use	6. IF INDIAN, ALLOTTEE OR TRIBE NAME N/A		
1. OIL GAS WELL WELL XX OTHER 2. NAME OF OPERATOR			7. UNIT AGREEMENT NAME N/A 8. FARM OR LEASE NAME
Getty 0il 3. Address of Open Drawet 510	P.L. Davis 9. WELL NO. #2E		
Drawet 510, Farmington, New Mexico 87401 Location of Well (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 1030'FSL & 1040'FEL			Basin Dakota 11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA
14. PERMIT NO.	15. ELEVATIONS (Show whethe	r df, rt, gr, etc.) 32 'GR	Sec. 26 T26N R11W 12. COUNTY OF PARISH 13. STATE San Juan New Mexi
16.	Other Data EQUENT REPORT OF:		
TEST WATER SH FRACTURE TREAT SHOOT OR ACIDIS REPAIR WELL (Other)	T MULTIPLE COMPLETE ABANDON* CHANGE PLANS	Completion or Recon	REPAIRING WELL ALTERING CASING ABANDONMENT* lits of multiple completion on Well mpletion Report and Log form.)
proposed work nent to this wo	ED OR COMPLETED OPERATIONS (Clearly state all perticular to the control of the lated top of the Ojo Alamo Forma	locations and measured and true vert	es, including estimated date of starting anticul depths for all markers and zones pert



S. I hereby certify that the foregoing is true and correct SIGNED LAPASCOTES George Lapascotes	Agent Consultant for TITLE Getty Oil Company	DATE July 27, 1979
(This space for Federal or State office use)		
APPROVED BYCONDITIONS OF APPROVAL, IF ANY:	TITLE	DATE
	0. 8	

nmole

*See Instructions on Reverse Side

Wax