5-USGS (Farmington) 1-Wexpro (Fmgtn) 1-We	expro (Salt Lake) 1-File
Form 9–331 Dec. 1973	Budget Bureau No. 42-R1424
UNITED STATES DEPARTMENT OF THE INTERIOR	5. LEASE NM 17781 =
GEOLOGICAL SURVEY	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)	7. UNIT AGREEMENT NAME
	8. FARM OR LEASE NAME 및 구선등 Paul Revere 중소국
1. oil gas well other	9. WELL NO. 429 1 437
2. NAME OF OPERATOR Dugan Production Corp.	10. FIELD OR WILDCAT NAME
3. ADDRESS OF OPERATOR Box 208, Farmington, NM 87401	WAW Fruitland PC 11. SEC., T., R., M., OR BLK. AND SURVEY OR
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.) 1120' FNL - 1520' FEL	AREA \$ 28 \$ 50 \$ 50 \$ 50 \$ 50 \$ 50 \$ 50 \$ 50 \$ 5
AT SURFACE: AT TOP PROD. INTERVAL:	12. COUNTY OR PARISH 13. STATE S
AT TOTAL DEPTH: 16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE.	14. API NO. CLERK D. COMPANDE
REPORT, OR OTHER DATA	15 ELEV TIONS (SHOW DF KDB, AND WD)
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT	61431 8 8 8 6 6 5 6
REQUEST FOR APPROVAL TO: TEST WATER SHUT-OFF FRACTURE TREAT SHOOT OR ACIDIZE REPAIR WELL RILL OR ALTER CASING	ogen brie enigon Flecci e Tilecci e sauré pu to ana of to ana of to ana of
REPAIR WELL	(NOTE: Export results of multiple completion or zone
MULTIPLE COMPLETE	GICAL N. M. Change bn. Form 9-330.)
ABANDON*	1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1
(other)	
17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly stat including estimated date of starting any proposed work. If well is d measured and true vertical depths for all markers and zones pertiner	lirectionally drilled, give subsurface locations and
Plan to plug and abandon as follows:	in the second se
	100 mg/mg/mg/mg/mg/mg/mg/mg/mg/mg/mg/mg/mg/m
 Pull 1½" O.D. tubing. Fill 2-7/8" O.D., 6.4#, 10R, NEUE tubing for 	or casing from PBFD 1342
to surface with 37 sx of cement.	on the state of th
 Install permanent dry hole monument. 	01.9 0.00 0.00 0.00 0.00 0.00 0.00 0.00
4. Fill all pits. 5. Clean and restore location as specified by the surface management ইন্ট্রিছ	
agency or landowner.	
Cut off or remove tie-downs.	
	· 프로그램 전환 전환 이 프로그램 이 시간 등 전 전 등을 보고 있는 사람들이 보고 있다.
Subsurface Safety Valve: Manu. and Type	Ft
18. Thereby gertify that the foregoing is true and correct	불일병보인 중요 유기한 현
SIGNED Jim L Jacobs TITLE Geologic	stare12-22-82==
(This space for Federal or State of	fice use)
APPROVED BY TITLE TITLE	—— ⁰ AS ÄMENDED
CONDITIONS OF AFFROYAL, IF ANI.	DE 0 2 0 409
	Clar Lies
See Instructions on Reverse	JAINIES F. SIMS DISTRICT ENGINEER
O NMOCA	