Form 3160-5 (June 1990)

Subsequent Report

Final Abandonment Notice

UNITED STATES DEPARTMENT OF THE INTERIOR **BUREAU OF LAND MANAGEMENT**

5. Lease Designation and Serial No.

New Construction

Water Shut-Off

Dispose Water

Non-Routine Fracturing

Conversion to Injection

	. 54.12.33	SF - 078433
Do not use this form for proposals to di	ID REPORTS ON WELLS 2 - 1 Pill 2: 33 ill or to deepen or reentry to a different reservoir. PERMIT—" for such proposals PARMIT—"	6. If Indian, Allottee or Tribe Name
SUBMIT IN TRIPLICATE		7. If Unit or CA, Agreement Designation
1. Type of Well Oil Gas Well Other 2. Name of Operator R C Resources Corp. 3. Address and Telephone No.		8. Well Name and No. Newsom No. 10R 9. API Well No. 30 - 045 - 24327
c/o Property Management&Consulting,P.O.Box 2596,Farminton,NM 87499 4. Location of Well (Footage, Sec., T., R., M., or Survey Description 1045 'FSL - 1215 'FWL, Section 20, T26N, R8W, NMPM 505-325-5220		10. Field and Pool, or Exploratory Area Basin Fruitland Coal 11. County or Parish, State
		San Juan, New Mexico
12. CHECK APPROPRIATE BOX	(s) TO INDICATE NATURE OF NOTICE, REI	PORT, OR OTHER DATA
TYPE OF SUBMISSION	TYPE OF ACTION	
Notice of Intent	Abandonment Recompletion	Change of Plans

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

Plugging Back T.A Lew Bes

Recompletion

Casing Repair

Altering Casing

Other

March 11 - April 20, 1999; Run GSL/GR/CCL from 2231 ' to 1200 '. Tag fill w/ gauge ring at 2233 '. Set CIBP @ 2180 1. Run CBL/VDL from 2178 ' to 1200 '. Pressure test casing & CIBP to 4000 psi. Perforate Fruitland Coal w/ 4-0.36" JSPF @ 1797 - 1802', 1808 - 10', 1835 - 37', 1844 - 46', 1876 - 78', 1908 -10', 1945 - 49', 1989 - 91', 2000 - 02', 2010 - 12', 2023 - 26', 2037 - 39', 2066 - 68', 2070 - 74', 2082 - 84', 2087 - 89', 2092 -95', 2107 - 11', 2125 - 27', and 2150 - 52'. Total holes - 204. Frac w/ 22,501 gals 20 # Delta Frac and 80,000 # 20/40 sand treated with sand wedge. AIR - 20 BPM. ATP - 3140 psi. ISIP - 1530 psi. Flow well back. Trip in hole with 1 1/4 " tubing to tag perforator debris at 1994'. Clean out to 2180 '. Land 1 1/4" production tubing at 1968' with seating nipple at 1936'. Flow well to clean up.



	Se - 8 - 8 - 8 - 8 - 8 - 8 - 8 - 8 - 8 -		
4. I hereby certify the foregoing is true and correct Signed	Tille Agent	AGCEPTED FOR BEOCH	
(This space for Federal or State office use) Approved by Conditions of approval, if any:	Title	DateSEP_0 8 1999	
Conditions of approval, it alify.		FLANCE OTON FIELD OFFICE	