



STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT
OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE

TONEY ANAYA
GOVERNOR

1000 RIO BRAZOS ROAD
AZTEC, NEW MEXICO 87410
(505) 334-6178

November 13, 1985

Ms. Barbara Norman
Union Texas Petroleum Corp.
P.O. Box 1290
Farmington, NM 87499

Re: Jicarilla F #7 K-28-26N-4W
Newsom A #6E G-15-26N-8W

Dear Barbara:

Annual packer leakage test on the referenced wells were inconclusive in proving zone separation.

Please reschedule and retest the wells in such a manner as to prove zone separation. Shut in both zones for a minimum of 3 days. Blow the higher pressured zone to the atmosphere or through separator to storage tank for as long as it takes to get a significant pressure drop.

Please advise this office at least 24 hours prior to test, so we may provide a witness.

Yours truly,

Charles Gholson
Oil & Gas Inspector

CG/dj

xc: Well File