

6 BLM, Fmn 1 Navajo Allotted
UNITED STATES 1 McHugh
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

1 File

Form Approved.
Budget Bureau No. 42-R1424

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil ☐ gas ☒ other ☐
2. NAME OF OPERATOR
Jerome P. McHugh
3. ADDRESS OF OPERATOR
P O Box 208, Farmington, NM 87401
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)
AT SURFACE: 1850' FNL - 1850' FEL
AT TOP PROD. INTERVAL:
AT TOTAL DEPTH:
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

5. LEASE
N00-C-14-20-7466
6. IF INDIAN, ALLOTTEE OR TRIBE NAME
Navajo Allotted
7. UNIT AGREEMENT NAME
8. FARM OR LEASE NAME
Quick Deal
9. WELL NO.
1
10. FIELD OR WILDCAT NAME
WAW Fruitland P.C.
11. SEC., T., R., M. OR BLK. AND SURVEY OR AREA
Sec 7 T26N R12W
12. COUNTY OR PARISH
San Juan
13. STATE
NM
14. API NO.
15. ELEVATIONS (SHOW DF, KDB, AND WD)
5922' GL

- REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF:
- | | | |
|----------------------|-------------------------------------|--------------------------|
| TEST WATER SHUT-OFF | <input type="checkbox"/> | <input type="checkbox"/> |
| FRACTURE TREAT | <input type="checkbox"/> | <input type="checkbox"/> |
| SHOOT OR ACIDIZE | <input type="checkbox"/> | <input type="checkbox"/> |
| REPAIR WELL | <input type="checkbox"/> | <input type="checkbox"/> |
| PULL OR ALTER CASING | <input type="checkbox"/> | <input type="checkbox"/> |
| MULTIPLE COMPLETE | <input type="checkbox"/> | <input type="checkbox"/> |
| CHANGE ZONES | <input type="checkbox"/> | <input type="checkbox"/> |
| ABANDON* | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| (other) | | |

(NOTE: Report results of multiple completion or zone change on Form 9-330.)

RECEIVED

JUN 27 1984

BUREAU OF LAND MANAGEMENT
FARMINGTON RESOURCE AREA

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Plan to plug and abandon well as follows:

1. Fill 2-7/8" OD, 6.4#, 10 Rd, NEUE tubing for casing from PBTD 1170' to surface using 33 sx class "B" cement.
2. Install permanent dry hole monument.
3. Fill all pits.
4. Clean well location of all equipment, pipe, junk and trash.
5. Complete surface restoration as specified by the surface management agency or landowner.
6. Remove tie-downs.

Subsurface Safety Valve: Manu. and Type _____

18. I hereby certify that the foregoing is true and correct

SIGNED Sherman E. Dugan TITLE Geologist DATE 6-25-84

(This space for Federal or State office use)

APPROVED BY _____ TITLE _____ DATE _____
CONDITIONS OF APPROVAL, IF ANY:

Set @ _____ Ft.
APPROVED
6-25-84
JUN 28 1984
MATHEW N. MILLENBACH AREA MANAGER FARMINGTON RESOURCE AREA