WILLIAM R. SPEER

CONSULTING GEOLOGIST Petroleum Club Plaza Bldg. Farmington, New Mexico 87401 P.O. BOX 255

PHONE 505-325-7789

Certified Professional Geologist # 1121

Petroleum and Mineral Evaluation and Management

June 8, 1983

New Mexico Dept. of Minerals Oil & Gas Division 1000 Rio Brazos Road Aztec, New Mexico 87410

Att'n. Mr. Frank Chavez

Re:Hole Deviation Surveys,
Oxoco Production Corp. #1 Serendipity
1650' fS1, 2310' fE1, S26-T26N-R13W,
San Juan Co., New Mexico

Dear Sir,

The following hole deviation surveys were made while drilling the above-cited Gallup well:

DEPTH	DEVIATION	
60 '	1 ₄ O	
230	1 ₂ O	
713	3/4 ⁰	
1754	1½ ^O	
2242	1½ ^O	
2656	10	MERRIVEM
3142	1 ⁰	WESE A A E D
3632	14 ⁰	10N 9 1983
4142	1 ¹ / ₄ °	
4651	14 ⁰	OIL CON. DIV.
5082	1½°	DIS1. 3
5120	1½°	

Very truly yours,

William R. Speer, Agent for OXOCO PRODUCTION CORP.

Subscribed and sworn to me this 8th day of June, 1983, by Wm. R. Speer

My commission expires 12-13-84