Form 3160-5 (November 1983) (Formerly 9-331)	UNITED ST DEPARTMENT OF T BUREAU OF LAND	THE INTERIO	SUBMIT IN TRIPLICA (Other instructions of verse side)	Expires Augus 5. LEASE DESIGNATION NO-G-8501-1	No. 1004-0135 et 31, 1985 N AND SERIAL NO.	
SUND (Do not use thin for	RY NOTICES AND to for proposals to drill or to use "APPLICATION FOR PER	REPORTS ON deepen or plug back	WELLS COM to a different reservoir.	0. IF INDIAN, ACLOTE	IS OR TRIBE NAME	
OIL GAR SELL 2	OTHER			7. UNIT AGREEMENT N	AMB	
2. NAME OF OPERATOR			MINGTON RESOURCE	- 	MA	
Basin Fuels, Ltd.				9. WILL NO.		
P.O. Box 50), Farmington,	N.M. 87499		1-Y	- Wides,	
4. LOCATION OF WELL (Rep. See also space 17 below. At surface	ort location clearly and in acc)		ctured Cliff			
	1090' FNL	11. SSC., T., B., M., OR SURVET OR ARE	11. SEC. T., S., M., OR BLE. AND Fruitland			
•	790' FEL			Sec. 13, T2	Coal Coal	
14. PERMIT NO.	BRHIT NO. 15. BLEVATIONS (Show whether DF, RT, GR, etc.)				12. COUNTY OR PARISH 18. STATS	
	600	2 GR	······································	San Juan	N.M.	
16.	Check Appropriate Box	To Indicate Nati	re of Notice, Report,	or Other Data		
NOT	ICE OF INTENTION TO:	i	# 01	BERQUENT REPORT OF:		
TEST WATER SHUT-OFF	PULL OR ALTER C.	18170	WATER SHUT-OFF	REPAIRING	WHILL	
PRACTURE TREAT	MULTIPLE COMPIL	1I	PRACTURE TREATMENT BEOOTING OR ACIDIZING	ALTERING (
RHOOT OR ACIDIES REPAIR WELL	ABANDON*	X	(Other)			
(Other)	MPLETED OPERATIONS (Clearly		(Note: Report re Completion or Rec	sults of multiple completion completion Report and Log for	on Well erm.)	
circulat	cased to TD 11 ted to surface. ig back TD (115	We intend	to fill the		ment	
·						
		• •		MEG	FIVER	
	•					
				TOO UU	1 8 1989	
••					ON. DIV.	
				OIL C	DIST. ?	
				•		
/		•			•	
	· ·				•	
18. I hereby gertify that the	ferending is true and corner	·t				
BIGNED A	5.1 Sun,	TITLE OV	vner	DATB9/1	L9/89	
(This space for Federal	er State office use)			A	palaised	
APPROVED BY		TITLE		DATE //	MARA	
CONDITIONS OF APPR	OVAL, IF ANT:	. 72040		Als	2 Ab al	
•	î,				/ /// way	
	•	See Instructions on	Reverse Side	Fir	A un Marga	
igggan ging ga na man mananan ka	ama, madama ja m seetises kira s	und gette word barrenstry o	bi morb mitfbfirdbei ber enn be	to any dispussionist us by	reacy of the	

BUREAU OF LAND MANAGEMENT 1235 La Plata Highway Farmington, New Mexico 87401 Phone (505) 327-5344

Attachment to Notice of

Re: Permanent Abandonment

Intention to Abandon

Well: 14 Napre

CONDITIONS OF APPROVAL

- 1. Plugging operations authorized are subject to the attached "General Requirements for Permanent Abandonment of Wells on Federal Leases."
- 2. Mark Kelly with the Farmington Office is to be notified at least 24 hours/before the plugging operations commence (505) 327-5344.
- 3. Blowout prevention equipment is required.
- 4. The following modifications to your plugging program are to be made (when applicable):

Office Hours: 7:45 a.m. to 4:30 p.m.

. ×

GENERAL REQUIREMENTS FOR PERMANENT ABANDONMENT OF WELLS ON FEDERAL AND INDIAN LEASES FARMINGTON RESOURCE AREA

- 1. Secure prior approval either on a Sundry Notice (Form 3160-5) or verbally from the Fluids Drilling & Production Section at this office before changing the approved plugging program.
- 2. Plugging equipment used shall have separate mixing and displacement pumps and a calibrated tank to assure proper displacement of plugs. The Operator is responsible for providing all measuring devices needed to assure proper measurement of materials being used.
- 3. A proper tank or pit will be used to contain all fluids pumped from the well during plugging operations. Unattended pits are to be fenced.
- 4. All cement plugs are to be placed through tubing (or drillpipe) and shall be a minimum of 100 feet in length with 50% excess inside casing or 100% excess when plug is set in open hole or squeezed into perforations. 15.6#/gal slurry weight is to be used when using class B neat cement or when CaCl₂ is used. Use the recommended slurry weight of other type cements when they are used (Class C, Pozzolan etc.).
- 5. Any cement plugs placed when well is not full of fluid, or when well may be taking fluid, (i.e. across perfs-unless bridge plug or retainer is used, across bad csg., or fresh water formations) will be tagged (touched) after cement has set to verify proper location.
 - 5a. Testing The first plug below the surface plug shall generally be tested by either tagging the plug with the working pipe string, or pressuring to a minimum pump (surface) pressure of 1000 psig, with no more than a 10 percent drop during a 15-minute period (cased hole only). If the integrity of any other plug is questioned, it must be tested in the same manner. Also, any cement plug which is the only isolating medium for a fresh water interval or a zone containing a valuable mineral deposit should be tested by tagging with the drill string.
- 6. Mud must be placed between plugs. Plugging mud is to be made up with a minimum of 15 lbs/bbl of sodium bentonite, and a nonfermenting polymer.

 Minimum consistency of plugging mud must be 9 lbs/gal and with a minimum viscosity of 50 sec/qt. Fresh water is to be utilized for mixing mud.
- 7. Following the placement of a cement plug, the withdrawl rate for at least the length of the cement plug shall not exceed 30 ft/min, in order to minimize the contamination of the plug.

- 8. Within 30 days after plugging work is completed, file a Sundry Notice (Subsequent Report of Abandonment, Form 3160-5), in quintuplicate with Area Manager, Bureau of Land Management, 1235 La Plata Highway, Farmington, NM 87401. The report should give in detail the manner in which the plugging work was carried out, the extent (by depths) of cement plugs placed, and the size and location (by depths) of casing left in the well. Show date well was plugged.
- 9. All permanently abandoned wells are to be marked with a regulation marker (4" pipe extending 4' above the ground line) containing the information as specified in 43 CFR 3162.6(d). Unless otherwise approved.
- 10. After plugging work is completed the surface is to be rehabilitated in accord with instructions from the Fluids Surface Management Section of the Farmington Resource Area Office.

All above are minimum requirements. The period of liability under the bond of record will not be terminated until the lease is inspected and surface work approved.

Please advise this office when the well location is ready for final inspection.

Failure to comply with the above conditions of approval may result in an assessment for noncompliance and/or a Shut-in Order being issued pursuant to 43 CFR 3163.1.

You are further advised that any instructions, orders or decisions issued by the Bureau of Land Management are subject to administrative review pursuant to 43 CFR 3165.3 and appeal pursuant to 43 CFR 3165.4 and 43 CFR 4.700.