asing S sg.Perf.		.w [.]	Sx.	. ft. Int		•———	.w	Spd Cu. ft. Sx. Pr Prod. Stim.			w	Cu. ft. Sx. T.		·8 @	7 Gas
P	BO/D MCF/D_Afte	or	_Hrs.	SICP_		PSI After		Grav Days GOR		1st De	el Gas				A N S
TOPS			NITD		X	Wel			TEST DAT		71. <u>UII</u>				
Ojo Alamo			C-103		_	Plat		X	Schd.	PC	0	PW	1 00	T	T
Kirtland			C-104			Elect	ric Log				-		PD	D	Ref.No
Fruitland		1		I		C-12					 	 		 -	
Pictured Cliffs			Ditr			Dfa					ļ —	 		 	
Chacra			Datr			Dac		· · · · · · · · · · · · · · · · · · ·				 	ļ		
Cliff House												-		 	-
Menefee								i	<u> </u>			 -		<u> </u>	↓
Point Lookout												 		ļ	<u> </u>
Mancos												 		<u> </u>	
Gallup												 			
Greenhorn									 			 			<u> </u>
Dakota												 -		 .	↓
Entrada															
		$\neg \neg$													
						ACI	es W/320] .				

Cowsaround 27 #12 L-27-26N-12W

NASSAU RESOURCES, INC.



United States Department of the Interior

BUREAU OF LAND MANAGEMENT Farmington Resource Area 1235 Laplata Highway Farmington, New Mexico 87401



NM-30015 et al. (WC) 3162.3-1.0 (019)

JUL 9 1991

Nassau Resources, Inc. P.O. Box 809 Farmington, NM 87499

Gentlemen:

Enclosed are your Applications for Permit to Drill well Nos:

- 1. 4 Carracas Unit 19 B sec. 19, T. 32 N., R. 4 W., Rio Arriba County, New Mexico, lease NM-30015.
- 2. 8 Carracas Unit 29 B sec. 29, T. 32 N., R. 4 W., Rio Arriba County, New Mexico, lease NM-28277.
- 3. 12 Cowsaround 27 sec. 27, T. 26 N., R. 12 W., San Juan County, New Mexico, lease NM-0557296-A.

As discussed with Fran Perrin of your company, on July 3, 1991, the subject APDs are rescinded and returned due to drilling not being commenced within the approved period of time.

You are required to request surface rehabilitation instructions from this office if construction activities occurred on the referenced drill site. If this office does not receive comment within 30 days, we will presume that no construction occurred and proceed accordingly. Later discovery that construction activities have in fact occurred, may result in assessment of liquidated damages.

Sincerely,

LA LEND L. Keity

John L. Keller Chief, Branch of Mineral Resources

Enclosure

cc:

New Mexico Oil Conservation Division, 1000 Rio Brazos Rd., Aztec, NM 87410

ABANDONED LOCATION OIL CON. DIV.