

Day B #8

A-07-27N-08W

UNION OIL CO. OF CALIF.

30-045-28201

09-04-90

F. Loc. 836/N: 1335/E Elev. 6272 GL Spd. _____ Comp. _____ TD. _____ PB. _____
 Casing S. _____ Cu. ft. _____ Sx. Int. _____ W. _____ Sx. Pr. _____ W. _____ Sx. T. _____
 Csg. Perf. _____ Prod. Stim. _____

80/D _____ Grav. _____ 1st Del. Gas _____
 I.P. _____ MCF/D After _____ Hrs. SICP _____ PSI After _____ Days GOR _____ 1st Del. Oil _____

TOPS		NI/D	X	Well Log	TEST DATA							
Ojo Alamo		C- 103		Plat	X	Schd.	PC	Q	PW	PD	D	Ref.No.
Kirtland		C- 104		Electric Log								
Fruitland				C- 122								
Pictured Cliffs		Ditr		Dfa								
Chacra		Datr		Dac								
Cliff House		Order DO-38										
Menefee												
Point Lookout												
Mancos												
Gallup												
Greenhorn												
Dakota												
Entrada												
				Acres E/320								

P
o
o

BasinFrCoal Co. SJ S 07 T 27N R 08W UA Oper. Union Oil Co. of Cal Lsa. Day B

No. 8



United States Department of the Interior

BUREAU OF LAND MANAGEMENT
Farmington Resource Area
1235 Laplata Highway
Farmington, New Mexico 87401



IN REPLY REFER TO:
SF-078571 et al. (WC)
3162.3-1 (019)

Union Oil Company of California
P.O. Box 2074
Farmington, NM 87499

OCT. 1 9 1991

Gentlemen:

Enclosed are your Applications for Permit to Drill well Nos:

- ✓ 1. 8 Day B, sec. 7, T. 27 N., R. 8 W., San Juan County, NM,
lease SF-078571.
- ✓ 2. 297 Rincon Unit, sec. 34, T. 27 N., R. 7 W., Rio Arriba County, NM,
lease SF-080213.
- ✓ 3. 302 Rincon Unit, sec. 25, T. 27 N., R. 7 W., Rio Arriba County, NM,
lease SF-079321.
- ✓ 4. 299 Rincon Unit, sec. 6, T. 26 N., R. 6 W., Rio Arriba County, NM,
lease SF-079301-A.

The subject APDs are rescinded and returned due to drilling not being commenced within the approved period of time.

You are required to request surface rehabilitation instructions from this office if construction activities occurred on the referenced drill site. If this office does not receive comment within 30 days, we will presume that no construction occurred and proceed accordingly. Later discovery that construction activities have in fact occurred, may result in assessment of liquidated damages.

Sincerely,

John L. Keller
Chief, Branch of Mineral Resources

4 Enclosures

cc:

New Mexico Oil Conservation Division, 1000 Rio Brazos Rd., Aztec, NM 87410

ABANDONED LOCATION:

RECEIVED
OCT 21 1991
OIL CON. DIV
DIST. 3