i rile Mud C Form 3160-5 UNITED STATES PORM APPROVED (June 1990) deet Bureau No. 1004-0115 DEPARTMENT OF THE INTERIOR Expires: March 31, 1993 **BUREAU OF LAND MANAGEMENT** S. Lease Designation and Serial No. SF-078156A
6. If Indian, Allottee or Tribe Name SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to deepen or reentry to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals 7. If Unit or CA, Agreement Designation SUBMIT IN TRIPLICATE 1. Type of Well Well X Gas Other 8. Well Name and No. 2. Name of Operator Cisco Com #91 Dugan Production Corp. 9. API Well No. J. Address and Telephone No. 30 045 28805 P.O. Box 420, Farmington, NM 87499 10. Field and Pool, or Exploratory Area (505) 325-1821 4. Location of Well (Footage, Sec., T., R., M., or Survey Description) Basin Fruitland Coal 11. County or Parish, State 790' FSL & 790' FWL (Unit M) San Juan, New Mexico Sec. 34, T26N, R13W 12. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA TYPE OF SUBMISSION TYPE OF ACTION Notice of Intent Abandonment Change of Plans Recompletion **New Construction** Subsequent Report Plugging Back Non-Routine Fracturing Casing Repair Water Shut-Off Final Abandonment Notice Altering Casing Conversion to Injection Other Spud & Surface Casing Dispose Water (Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.) 13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)* minutes before drilling out cement - held OK.

Move in & rig up Wayne Smith Drilling. Spudded 9-1/8" hole @ 1130 hrs 11/16/92. Drilled surface - 125'. Ran 3 jts. 7", 23#, J-55 casing landed at 121'. Pump 5 bbls water. Cement with 50 sx class "B" neat cement with 28 CaCl, (59 cu.ft.). Plug down at 1530 hrs 11/16/92. Circulate 2 bbls cement. W.O.C. 12 hrs.

Nippled up BOP - tested surface casing and BOP 600 psi for 30 minutes before drilling out cement - held OK.

Nippled up BOP - tested surface casing and BOP 600 psi for 30 minutes before drilling out cement - held OK.

Oil CON. Drive Annual Company of the state of the superior of the state of