I		
ı	 	
ı		
I	 	
I		
ŀ	 	
ı		
н	i 1	

(SUBMIT IN TRIPLICATE)

UNITED STATES DEPARTMENT OF THE INTERIOR **GEOLOGICAL SURVEY**

Budget	Bureau No.	42-R358.4.
Form A	poroved.	

Land Office Santa Fe

079049 Nº 800.33

DEEPEN WELL

NOTICE OF INTENTION TO THE DOODS	m Well	XX	SUBSEQUENT P	EPORT OF WATER	SHITT OFF		
NOTICE OF INTENTION TO CHANGE PLANS				EPORT OF SHOOT			
NOTICE OF INTENTION TO TEST WATER SHUT-	1			EPORT OF ALTERI			,
NOTICE OF INTENTION TO RE-DRILL OR REPAI	R WELL			EPORT OF RE-DRI			
NOTICE OF INTENTION TO SHOOT OR ACIDIZE				EPORT OF ABANDO			
NOTICE OF INTENTION TO PULL OR ALIER CAS	ING	31		Y WELL HISTORY.			
NOTICE OF INTENTION TO ABANDON WELL			·				
(INDICATE ABOVE	BY CHECK MARK	C NATU	RE OF REPORT, I	IOTICE, OR OTHER	DATA)		
				March 13	<u> </u>		19_5
He Pherson		(N)	n		(-		
ell No. 1 is located 99	ft. from	- 18	line and	1650 ft. fro	om E lin	e of sec.	33
NW 1/4 Sec. 33 'f	'-28-N	R-6	H	N.M.P.M.			
Besin Dekota		-	-		New Max	rico	
(Field)	(County o	r Subd	iba ivision)		(State or Terri		
ne elevation <i>bl ENI BEHAM Abbl h</i> i		•	6597 ft OF WORK	G.L.			
rate names of and expected depths to objective ing 1	DETAI sands; show size points, and all o	LS (OF WORK	us of proposed case ed work)			
ate names of and expected depths to objective ing :	DETAI sands; show size points, and all o	LS (OF WORK ghts, and length nportant propos D. of 59	of proposed can ed work)	reximate	Ly 7850.	
tate names of and expected depths to objective ing : I've in retary and deepen from 4-1/2" OD 10.50# J-55 ca 1/2 comented w/200 ax area V. Tool set 100" below Bas	DETAI sands; show size points, and all of the presentating to Tand shee a	LS (es, weighther in ther in	OF WORK ghts, and length nportant propos D. of 59 Perfor	of proposed cased work) 02 to appi	reximate rec form	ly 7850. Rtion.	
ve in retary and deepen from 4-1/2" OD 10.50# J-55 ca	DETAI sands; show size points, and all of the presentating to Tand shee a	LS (es, weighther in ther in	OF WORK ghts, and length nportant propos D. of 59 Perfor	of proposed cased work) 02 to appi	reximate rec form	ly 7850. Rtion.	
ve in retary and deepen from 4-1/2" OD 10.50# J-55 ca	DETAI sands; show size points, and all of the presentating to Tand shee a	LS (es, weighther in ther in	OF WORK ghts, and length nportant propos D. of 59 Perfor	of proposed cased work) 02 to appi	reximate rec form	ly 7850. Rtion. MV thru	May be seen to see the
we in retary and deepen from 4-1/2" OD 10.50# J-55 ca	DETAI sands; show size points, and all of the sands; show size presentation presentation to Tand sheet all of KV.	LS (es, weighther in ther in	OF WORK ghts, and length nportant propos D. of 59 Perfor	of proposed cased work) 02 to appi	reximate rec form	ly 7850. Rtion.	Man Care Control of the Control of t
we in retary and deepen from 4-1/2" OD 10.50# J-55 cat/2 cemented w/290 ax area V. Toel set 100" helow Bas	DETAI sands; show size points, and all of presents and sheet and sheet are of MV.	LS (OF WORK shts, and length nportant propos D. of 59 Perfor sufficien	of proposed cased work) 02 to appliate and fi	reximately rec formation cover	MV thru	om

Farmington, New Mexico

Title Kgr. Operations Dept.