

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE*
(Other instructions on re-
verse side)

Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

Cont. No. 285

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

Jicarilla Apache

7. UNIT AGREEMENT NAME

-

8. FARM OR LEASE NAME

Jicarilla #7

9. WELL NO.

1

10. FIELD AND POOL, OR WILDCAT

Boulder Manos

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

Sec. 11-28N-1W

1.

OIL ☒ GAS ☐
WELL WELL OTHER

2. NAME OF OPERATOR

Skelly Oil Company

3. ADDRESS OF OPERATOR

Box 730 - Hobbs, New Mexico

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface

660' FSL & 660' FWL Sec. 11-28N-1W

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

7359' DF

12. COUNTY OR PARISH

Rio Arriba

13. STATE

New Mexico

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

☐
☐
☐
☐
☐

PULL OR ALTER CASING

☐
☐
☐
☐
☐

FRACTURE TREAT

MULTIPLE COMPLETE

SHOOT OR ACIDIZE

ABANDON*

REPAIR WELL

CHANGE PLANS

(Other)

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

☐
☐
☐
☐
☐

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

☐
☐
☒
☐
☐

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Well Plugged and Abandoned in the following manner:

1. Moved in and rigged up pulling unit.
2. Pulled rods and tubing.
3. Rigged down and moved out pulling unit.
4. Moved in and rigged up Hydraulic Casing Jack.
5. Spotted cement plug at the following depths:
4255-3701' - 100 sacks
6. Shot 7" OD casing off at 2246' and pulled same.
7. Rigged down and moved out Hydraulic Casing Jack.
8. Moved in and rigged up pulling unit.
9. Spotted cement plugs at the following depths:
2292-2192' - 28 sacks - (Cut off point on 7" OD casing at 2246').
567- 467' - 37 sacks
10. Welded plate on top of 10-3/4" OD surface casing and installed 4" steel marker.
(No cement cap installed because of possible use as a Water Well by the Apache Tribe).
11. All intervals not cemented are filled with heavy mud laden fluid.
12. Plugging operations were completed on May 19, 1965.

Date work performed - April 21 & 22 and May 13, 14 & 17 thru 19, 1965.

18. I hereby certify that the foregoing is true and correct

SIGNED

(ORIGINAL) **H. E. Ash**
(SIGNED)

TITLE

Dist. Superintendent

DATE

May 20, 1965

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side

Instructions

General: This form is designed for submitting proposals to perform certain well operations, and reports of such operations when completed, as indicated, on Federal and Indian lands pursuant to applicable Federal law and regulations, and, if approved or accepted by any State, on all lands in such State, pursuant to applicable State law and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local, area, or regional procedures and practices, either are shown below or will be issued by, or may be obtained from, the local Federal and/or State office.

Item 4: If there are no applicable State requirements, locations on Federal or Indian land should be described in accordance with Federal requirements. Consult local State or Federal office for specific instructions.

Item 17: Proposals to abandon a well and subsequent reports of abandonment should include such special information as is required by local Federal and/or State offices. In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones, or other zones with present significant fluid contents not sealed off by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; mud or other material placed below, between and above plugs; amount, size, method of parting of any casing, liner or tubing purged; and the depth to top of any left in the hole; method of closing top of well; and date well site conditioned for final inspection looking to approval of the abandonment.

U.S. GOVERNMENT PRINTING OFFICE: 1963-O-685229
887-631



(SIGNED) H. E. A. (PRINTED)