Form 3160-5 (June 1907)  UNITED STATE  DEPARTMENT OF THE  BUREAU OF LAND MANAGE	INTERIOR F CODY	1
<u> </u>		SF079290-B
SUNDRY NOTICES AND RE		6. IF INDIAN, ALLOTTEE OR TRIBE NAME
Do not use this form for proposals to drill or to d	•	
Use "APPLICATION FOR PERM	IIT-" for such proposals	
SUBMIT IN TRIPLICATE		7. IF UNIT OR CA, AGREEMENT DESIGNATION
1. TYPE OF WELL		8. WELL NAME AND NO.
OIL WELL GAS WELL OTHER		SAN JUAN 28-7 UNIT #221
2. NAME OF OPERATOR		9. API WELL NO.
CONOCO INC.  3. ADDRESS AND TELEPHONE NO.		30-039-21064
		10. FIELD AND POOL, OR EXPLORATORY AREA
10 DESTA DR., SUITE 100W, MIDLAND, TX 79705-4500 (915) 686-5424  4. LOCATION OF WELL (Footage, Sec., T., R., M., or Survey Description)		Blanco Mesa Verde 11. COUNTY OR PARISH, STATE
880' FNL & 1830' FEL, SEC. 25, T28N, R7W, UNIT LTR 'E		
	TO INDICATE NATURE OF NOTICE, I	RIO ARRIBA, NM
TYPE OF SUBMISSION	TYPE	OF ACTION
Notice of Intent	Abandonment	Change of Plans
Subsequent Report	Recompletion to Mesa Verde Forr	
Final Abandonment Notice	Plugging Back	Non-Routine Fracturing
	Casing Repair Altering Casing	Water Shut-Off
	Other:	Conversion to Injection  Dispose Water
	outer.	(Note: Report results of multiple completion on Well Completion or
Recompletion Report and Log Form.)  13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is		
directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)		
	The second secon	
SEE ATTACHED STIMULATION SUMMAR		
		: : : : : : : : : : : : : : : : : : :
	UU JUN 1 0 th	
	1 8 1997	
	0[[[ CON. D[[ DIST. 3	
		<i>Y</i> Z
	misil 3	~0
	25 m	
14. I hereby certify that the foregoing is true and correct	The contract of the contract o	
$1 \qquad 1 \qquad$	DEBRA BEMENDER	EED
SIGNED NUMBER PENEUROLD	'	
	TITLE AGENT FOR CONOC	
(This space for Federal or State office use)		ACCEPTED FOR RECORD
APPROVED BY	TITLE	DATE
Sometiment of approval, it ally.		JUN 1 6 1997
Title 19 LL C. Cooking 4004 analysis the sales for	and the suitable and suite it.	
Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the Unites States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.		
* See Instruction on Pourme Side		

## CONOCO INC. SAN JUAN 28-7 #221

API # 30-039-21064 Section 25, T28N-R7W, UNIT LETTER B 880" FNL - 1830' FEL ATTACHMENT FOR BLM 3160-4, 3160-5 AND OCD C-104

5/27/97 MIRU, NDWH and NUBOP. POOH with 1 ½" TBG, laying down. RU wireline, set CIBP @ 5290'. Test CSG and CIBP to 3000 psi. OK.

RU wireline, run CBL from 5290' to 2300', was still showing to be good cement. RIH perforated 5081-86-89-5120-22-24-59-63-65-71-75-82-89-94-5202-21-23-25-31-33. With 2000 psi on CSG. Ran 1 jt. TBG and PKR, acidized with 500 gals. 15% HCL @ 11 BPM @ 2200 psi, avg. pressure. Good ball action, balled out. Had to shut down to repair 4 ½" CSG slips. Frac'd with 119,000# 20/40 Arizona. @ 50 BPM @ 2250 psi. ISIP 0 psi. Set CIBP @ 4760'. Test CSG to 3000 psi. OK. Perforate 4583-87-89-94-97-4601-03-10-18-39-45-50-52-59-63-67-72-4701-05-08. Perforated with 2000 psi. Total Fluid Pumped with FRAC 1910 BBLS. Slickwater.

Rig Up BJ. Acidize with 500 gals. 15% HCL @ with 30 ball sealers @ 12.3 BPM @ 1180 psi. Good Ball Action, balled Out. ISIP 300 psi. Retrieve Balls. Frac Cliffhouse with 2307 BBL of Slickwater with 85000# of 20/40 AZ., 6900# of SDC. @ 43.5 BPM @ 2920 psi max and avg. 2790 psi. ISIP 850 psi. Max Sand Con. 2#/gal.

RIH with 2 3/8" TBG and Mill, Tag Sand @ 4602'. Started Compressors and Cleaned Sand to CIBP @ 4760'. Drilled up CIBP @ 4760'. Continued in hole and Tagged Sand @ 5194'.

RIH Tagged Sand @ 5190'. Started Compressors and Cleaned Sand to 5290'. Circulated Clean, will Drywatch Thru the Night, Flowing thru ½" Choke.

Drywatched Thru the night, Tested M.V. Flowing Thru ½" Choke. TBG 280 psi, and CSG. 560 psi, approximately 1848 MCFPD. RIH Tagged Sand @ 5275' for 15' of Fill. Started Compressors and Cleaned Fill to CIBP @ 5290'. Drilling out CIBP. Drywatched Thru the Night. Flowing Thru 2" Line.

RIH Tagged Sand @ 5282' for 8' of Fill. Started Compressors and Cleaned Sand to CIBP @ 5290'. Drilled up CIBP @ 5290'. Continued in Hole and Tagged Fill @ 7365'. Started Cleaning Fill.

POOH with TBG and Mill. RIH with 2 3/8" TBG, SN and Mule Shoe. Tagged Fill @ 7385' for 10' of Fill. Started Compressors and Cleaned Sand to PBTD @ 7395'. Pulled Up and Landed TBG @ 7301' with 233 JTS. Of 2 3/8" TBG. This Depth W/O K.B.NDWH & NUBOP.

6/6/97 Rig Down and Move Off Location.