

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLICATE
(Other instructions on reverse side)

Docket Bureau No. 1004-0135
Expires August 31, 1985

5. LEASE DESIGNATION AND SERIAL NO.

NM-14923

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT ASSIGNMENT NAME

Valencia Canyon Unit

8. FARM OR LEASE NAME

9. WELL NO.

44

10. FIELD AND POOL, OR WILDCAT

Blanco Mesaverde/Nacimiento

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

SW/NE Sec 35, T28N, R4W

12. COUNTY OR PARISH 13. STATE

Rio Arriba

NM

1. OIL ☐ GAS ☐ OTHER ☒

2. NAME OF OPERATOR

Amoco Production Co.

3. ADDRESS OF OPERATOR

501 Airport Drive, Farmington, N M 87401

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.)

At surface

1800' FNL x 1520' FEL

14. PERMIT NO.

15. ELEVATIONS (Show whether DT, RT, GR, ETC.)

7298' GR

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

WELL OR ALTER CASING

MULTIPLE COMPLETION

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROMISED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

Moved in and rigged up service unit on 6-11-86. Loaded hole with 60 bbl. fresh water. Tripped out 2-3/8" tubing. Drilled out the bridgeplug set at 3100' with a 6-1/4" bit. Set tubing at 4140' to begin cementing. Spotted a 100' cement plug consisting of 24 cf Class B cement from 4023'-4123'. Spotted a 100' cement plug consisting of 24 cf of Class B cement from 3742'-3843'. Spotted a 100' cement plug consisting of 24 cf Class B cement from 3475'-3575'. Set a cement retainer at 2750'. Pumped 177 cf Class B cement and displaced with 10 bbl. of fresh water. Stung out of retainer and left a 1/2 bbl of cement on top of the retainer. Tripped in with tubing and spotted a 400' cement plug consisting of 94 cf Class B cement. Welded on a dry hole marker and released the rig on 6-13-86.

Approved as to plugging of the well bore.
Liability under bond is retained until
surface restoration is completed.

JUN 17 1986

I hereby certify that the foregoing is true and correct

SIGNED

BSShaw

TITLE Adm. Supervisor

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

APPROVED

DATE 6-19-86

JUN 24 1986

FARMINGTON RESOURCE AREA

*See Instructions on Reverse Side

NMOCC