Form 3160-5 (August 1999)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED				
OMB NO. 1004-0135				

	Expires: November	30.	2000
5.	Lease Serial No.		

SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals

SF-079522

abandoned well. Use form 3160-3 (APD) for such proposals.				6. If Indian, Allottee or Tribe Name			
SUBMIT IN TRIPLICATE - Other instructions on reverse side.				7. If Unit or CA/Agreement Name and/or No. SAN JUAN 28-5 UNI			
1. Type of Well Oil Well	8. Well Name and No. SAN JUAN 28-5 UNIT 73M						
Name of Operator BURLINGTON RESOURCES OIL	9. API Well No. 3003925663						
3a. Address 3401 EAST 30TH FARMINGTON, NM	3b. Phone No.(include are 505.326.9727	a code) 	10. Field and Pool, or Exploratory Area BLANCO MV/BASIN DK				
4. Location of Well (Footage, 2) 2075FEL 765FSL	11. County or Parish, and State RIO ARRIBA NM						
12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA							
TYPE OF SUBMISSION TYPE OF ACTION					<u>-</u>		
□ Notice of Intent □ Acidize □ Deepen □ Production □ Alter Casing □ Fracture Treat □ Reclamatio □ Casing Repair □ New Construction □ Recomplete		mplete orarily Abandon	□ Water Shut-Off □ Well Integrity □ Other				
13. Describe Proposed or Completed Operation	n (clearly state all pertinent details, incl	uding estimated starting date of a	ny proposed w	ork and approximate duratio	n thereof.		

3. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be files within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)

See attached



Electronic Submission #3691 verified by the BLM Well Information System for E Committed to AFMSS for processing by Maurice Johnson on 04/19/2001 Name (Printed/Typed) PEGGY COLE	BURLINGT Title	ON RESOURCES OIL & GAS Sent to	
Signature THIS SPACE FOR FEDER	Date AL OR S	04/18/2001 STATE OFFICE USE	· FOR RECOR
Approved By Conditions of approval, if any, are attached. Approval of this notice does not warr certify that the applicant holds legal or equitable title to those rights in the subject which would entitle the applicant to conduct operations thereon.	lease	Title Office	JML - UFFICE

```
MIRU. ND WH. NU BOP. SDON
4 - 5 - 01
```

TOOH w/254 its 2 3/8" tbg. TIH w/4 1/2" CIBP, set @ 5050'. Load hole 4-6-01

w/125 bbl 2%

KCl wtr. Pump into csq leak. Communication through bradenhead valve.

TOOH.

TIH w/7" pkr, set @ 30'. PT csq below pkr to 3000 psi, OK. Reset pkr

@ 10'.

PT to 3000 psi, OK. Isolate csq leak @ approximately 2" below WH.

TOOH w/pkr.

Dig out around 9 5/8" csq. SDON.

TIH to CIBP. Circ hole clean. TOOH. ND BOP. Run hose between 9 5/8" & 4-7-01 7" csq.

Displace w/wtr. SDON.

Cut off 9 5/8" & 7" csq. Reinstall 9 5/8" csq head, 7" mandrel & tbq 4-8-01 spool.

NU BOP. PT 7" csq to 3000 psi/15 min, OK. WO frac crew.

TIH, perf Lewis w/1 SPF @ 4530, 4532, 4536, 4562, 4566, 4570, 4574, 4580, 4586,

4590, 4593, 4603, 4620, 4625, 4633, 4664, 4678, 4685, 4703, 4708,

4712, 4717,

4724, 4730, 4740, 4748, 4760, 4769, 4777, 4781, 4788, 4807, 4838,

4905, 4926,

4948, 4953, 4970, 4987, 4994' w/40 0.3" diameter holes total. Acidize

w/1260

gal 10% acetic acid. Frac Lewis w/807 bbl 20# linear gel, 1,316,000 SCF N2,

200,000# 20/40 Brady sd. CO after frac.

4-11-01 Blow well & CO.

Blow well & CO. TOOH. TIH $w/3\ 7/8"$ mill to 4843'. Blow well & CO. 4-12-01

Establish

circ. Mill out CIBP @ 5050'. TIH, blow well & CO.

4-13/15-01 Blow well & CO.

4-16-01 Blow well & CO. TOOH w/mill. TIH, blow well & CO. TOOH. TIH w/255 jts 2 3/8"

4.7# J-55 EUE tbg, landed @ 7953'. (SN @ 7920'). ND BOP. NU WH. RD.

Riq

released.