

U.S. GEOLOGICAL SURVEY
 BUREAU OF MINERAL INVESTIGATION
 WASHINGTON, D. C. 20508
 FIELD OFFICE NO. 32-27-12
 TITLE WATER SHUT-OFF

NAME OF COMPANY W. O. Don 1500, Farmington, New Mexico
 ADDRESS W. O. Don 1500, Farmington, New Mexico
 CITY Farmington, New Mexico
 COUNTY San Juan STATE New Mexico
 ZIP CODE 88401

DATE OF NOTICE 3-20-68
 DATE OF REPORT 3-20-68
 NAME OF AGENT Sullivan F
 TITLE OF AGENT Agent

16. Check appropriate box to indicate nature of notice, report, or other data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
WATER SHUT-OFF	☐	WATER SHUT-OFF	☐
FRACURE TREATMENT	☐	FRACURE TREATMENT	☐
SHOOTING OR ACIDIZING	☐	SHOOTING OR ACIDIZING	☐
REPAIRING WELL	☐	REPAIRING WELL	☐
ALTERING CASING	☐	ALTERING CASING	☐
ABANDONMENT*	☐	ABANDONMENT*	☐

(Note: Report results of multiple completion on Well Completion or Recombination Report and Form 1000)

17. Describe in detail the operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any operations. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

(Est. date to start work 4-1-68)

1. Load hole with mud laden fluid.
2. Squeeze Gallup perforations.
3. Shoot pipe loose at free point and pull.
4. Spot 100' cement plug 50' in and 50' out of stub.
5. Spot 100' cement plug across top of picture cliff.
6. Spot 100' cement plug at base of Ojo Alamo.
7. Place cement plug in top of surface with welded marker in place.
8. Clean location.



RECEIVED
 MAR 29 1968
 U. S. GEOLOGICAL SURVEY
 FARMINGTON, N. M.

18. I hereby certify that the foregoing is true and correct

SIGNED Jim Pagan TITLE Agent DATE 3-20-68

(This space for Federal or State office use)

APPROVED BY _____ TITLE _____ DATE _____

COPIES OF APPROVAL, IF ANY:

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPPLICATE*
(Other instructions on re-
verse side)

Form Approved.
Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

SF-078858

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐

7. UNIT AGREEMENT NAME

2. NAME OF OPERATOR

El Paso Products Company

8. FARM OR LEASE NAME

Sullivan F

3. ADDRESS OF OPERATOR

P. O. Box 1560, Farmington, New Mexico

9. WELL NO.

4

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface

10. FIELD AND POOL, OR WILDCAT

Gallegos Gallup

11. SEC., T., R., M., OR E.L.E. AND
SURVEY OR AREA

330'S, 2310'E, 27-N, 12-W

32-27-N, 12-W

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

5904'GR

12. COUNTY OR PARISH

13. STATE

San Juan

New Mexico

16.

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐

FRACTURE TREAT ☐

SHOOT OR ACIDIZE ☐

REPAIR WELL ☐

(Other) ☐

PULL OR ALTER CASING ☐

MULTIPLE COMPLETE ☐

ABANDON* ☒

CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐

FRACTURE TREATMENT ☐

SHOOTING OR ACIDIZING ☐

(Other) ☐

REPAIRING WELL ☐

ALTERING CASING ☐

ABANDONMENT* ☐

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any
proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones perti-
nent to this work.)*

(Est. date to start work
4-1-68)

1. Load hole with mud laden fluid.
2. Squeeze Gallup perforations.
3. Shoot pipe loose at free point and pull.
4. Spot 100' cement plug 50' in and 50' out of stub.
5. Spot 100' cement plug across top of picture cliff.
6. Spot 100' cement plug at base of Ojo Alamo.
7. Place cement plug in top of surface with welded marker in place.
8. Clean location.



RECEIVED

MAR 29 1968

U. S. GEOLOGICAL SURVEY
FARMINGTON, N. M.

18. I hereby certify that the foregoing is true and correct

SIGNED

Jim Papp

TITLE Agent

DATE 3-20-68

(This space for Federal or State office use)


APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side



UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIPLICATE*
(Other instructions on re-
verse side)Form approved.
Budget Bureau No. 42-B1424.

5. LEASE DESIGNATION AND SERIAL NO.

ST - 878858

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Sullivan

9. WELL NO.

4-7

10. FIELD AND POOL, OR WILDCAT

Gallup-Gallagos

11. SEC. T., R., M., OR BLK. AND
SURVEY OR AREA

Sec. 32, T27N, R12W

NMPM

12. COUNTY OR PARISH

San Juan

13. STATE

New Mexico

1.

OIL ☒ GAS ☐
WELL WELL OTHER

2. NAME OF OPERATOR

El Paso Products Company

3. ADDRESS OF OPERATOR

P. O. Box 1560, Farmington, New Mexico 87401

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface

330'/S, 2310'/E, Sec. 32, T 27 N, R 12 W

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

5904' GR

16.

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐FRACTURE TREAT ☐SHOOT OR ACIDIZE ☐REPAIR WELL ☐

(Other)

PULL OR ALTER CASING ☐MULTIPLE COMPLETE ☐ABANDON* ☐CHANGE PLANS ☐


SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐FRACTURE TREATMENT ☐SHOOTING OR ACIDIZING ☐

(Other)

REPAIRING WELL ☐ALTERING CASING ☐ABANDONMENT* ☒(NOTE: Report results of multiple completion or Well
Completion or Recompletion Report and Log form.)17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any
proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones perti-
nent to this work.)*Start Operations - 7-30-68
Finish Operations - 8-5-68

1. Load hole with mud laden fluid.
2. Squeeze Gallup perforations at 3053' to 4833', 25 sx cmt.
3. Shoot pipe loose at free point 2202' and pull.
4. Spot 30 sx cmt, 4% gel at 2254' to 2109' in and out of stub.
5. Spot 30 sx cmt, 4% gel at 1195' to 1085' top Pictured Cliffs
6. Ojo Alamo behind surface casing.
7. Spot 10 sx cmt top surface casing with welded marker in place.
8. Clean location.



RECEIVED

SEP 27 1968

U. S. GEOLOGICAL SURVEY

18. I hereby certify that the foregoing is true and correct

Original SIGNED by: Jim Payne

TITLE Agent

DATE August 29, 1968

(This space for Federal or State office use)

APPROVED BY
CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

*See Instructions on Reverse Side

Instructions

General: This form is designed for submitting proposals to perform certain well operations, and reports of such operations, when completed, as indicated, on Federal and Indian lands pursuant to applicable Federal law and regulations, and, if approved or accepted by any State, on all lands in such State, pursuant to applicable State law and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local, area, or regional procedures and practices, either are shown below or will be issued by, or may be obtained from, the local Federal and/or State office.

Item 4: If there are no applicable State requirements, locations on Federal or Indian land should be described in accordance with Federal requirements. Consult local State or Federal office for specific instructions.

Item 17: Proposals to abandon a well and subsequent reports of abandonment should include such special information as is required by local Federal and/or State offices. In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones, or other zones with present significant fluid contents not sealed off by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; mud or other material placed below, between and above plugs; amount, size, method of parting of any casing, liner or tubing pulled and the depth to top of any left in the hole; method of closing top of well; and date well site conditioned for final inspection looking to approval of the abandonment.