NO. OF COPIES RECEIVED	Form C -103
DISTRIBUTION	Supersedes Old C-102 and C-103
SANTA FE / NEW MEXICO OIL CONSERVATO COMISSION FILE U.S.G.S. LAND OFFICE	Effective 1-1-65
U.S.G.S.	5a. Indicate Type of Lease
LAND OFFICE	XXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXX
U.S.G.S.  LAND OFFICE  OPERATOR  OIL DIST. 3	5. State Oil & Gas Lease No. SF-078089
SUNDRY NOTICES AND REPORTS ON WELLS  (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
OIL GAS OTHER-	7. Unit Agreement Name
2. Name of Operator	8, Farm or Lease Name
Beta Development Co.  3. Address of Operator	Hancock Federal
	9, Well No.
125 Petr. Club Plaza, Farmington, New Mexico 4. Location of Well	10. Field and Pool, or Wildcat
UNIT LETTER K , 1850 FEET FROM THE SOUTH LINE AND 1850 FEET FROM	Basin Dakota
, , , , , , , , , , , , , , , , , , ,	
THE West LINE, SECTION 22 TOWNSHIP 27 N RANGE 11 W NMPM.	
15. Elevation (Show whether DF, RT, GR, etc.)	12. County
6364° G.I.	San Juan
Check Appropriate Box To Indicate Nature of Notice, Report or Oth	er Data   REPORT OF:
NOTICE OF INTENTION TO:	REFORT OF:
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK	ALTERING CASING
TEMPORARILY ABANDON COMMENCE DRILLING OPNS.	PLUG AND ABANDONMENT
PULL OR ALTER CASING CHANGE PLANS CASING TEST AND CEMENT JQB	
OTHER	
17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including	estimated date of starting any proposed
work) SEE RULE 1103.	
4/2/68 Rigged up workever unit, removed well head, rigged up blow out p tbg, tbg stuck on bottom. Tried to break circulation w/rig pump	reventor. Latched orto
Pumped in 45 bbls hot oil down the 2100%. Worked the trying	to pull same loose.
Waited on free point & tbg. cutter.	
4/3/68 Rigged up, ran free point & found tbg. stuck 6590°. Ran chemi	cal mittam cut that off
@ 6578'. Pulled out 30 stands and circ. out 2,000' heavy drlg.	cal cutter, cat the ori
at a set 1000t told and 0 shale Cime 1 1/0 has on to	mud. Ran in 20 stands
circ. out 1200° drlg. mud, sand & shale. Circ. 1-1/2 hrs. on to	mud. Ran in 20 stands p of fish 3 6578, PCH.
circ. out 1200° drlg. mud, sand & shale. Circ. 1-1/2 hrs. on to Recovered 204 jts & 4° piece (total 6578°); left 2 jts. & 27° pi	mud. Ran in 20 stancis p of fish 3 6578*, PCH. ece in hole. Picked up
circ. out 1200° drlg. mud, sand & shale. Circ. 1-1/2 hrs. on to Recovered 204 jts & 4° piece (total 6578°); left 2 jts. & 27° pi 3" Bowen jars w/overshot, WIH w/rented string of 2" tbg., caught Jarred on fish 1-1/2 hrs. Jarred fish loose, PCH. Recovered 2	mud. Ran in 20 stancis p of fish 3 6578, PCH. ece in hole. Picked up top of fish 6578.
circ. out 1200° drlg. mud, sand & shale. Circ. 1-1/2 hrs. on to Recovered 204 jts & 4° piece (total 6578°); left 2 jts. & 27° pi 3" Bowen jars w/overshot, WIH w/rented string of 2" tbg., caught Jarred on fish 1-1/2 hrs. Jarred fish loose, PCH. Recovered 2 1-1/2" tbg. WIH w/3-7/&" bit on 2" tbg.	mud. Ran in 20 stands p of fish 3 6578, PCH. ece in hole. Picked up top of fish 6578, 3ts. & 27 piece of
circ. out 1200° drlg. mud, sand & shale. Circ. 1-1/2 hrs. on to Recovered 204 jts & 4° piece (total 6578°); left 2 jts. & 27° pi 3" Bowen jars w/overshot, WIH w/rented string of 2" tbg., caught Jarred on fish 1-1/2 hrs. Jarred fish loose, PCH. Recovered 2 1-1/2" tbg. WIH w/3-7/2" bit on 2" tbg.  4/4/68 CO to 6684°. Circ. 2-1/2 hrs. PCH. L.D. 2" tbg, Welex ran gau	mud. Ran in 20 stands p of fish 3 6578*, PCH. ece in hole. Picked up top of fish 6578*. §ts. & 27* piece of ge ring to 6530*. Ran
circ. out 1200° drlg. mud, sand & shale. Circ. 1-1/2 hrs. on to Recovered 204 jts & 4° piece (total 6578°); left 2 jts. & 27° pi 3" Bowen jars w/overshot, WIH w/rented string of 2" tbg., caught Jarred on fish 1-1/2 hrs. Jarred fish loose, POH. Recovered 2 1-1/2" tbg. WIH w/3-7/2" bit on 2" tbg.  4/4/68 OD to 6684°. Circ. 2-1/2 hrs. POH. L.D. 2" tbg, Welex ran gauge Baker Model "D" production packer on wire line, set 9 6474°. WI	mud. Ran in 20 stands p of fish 3 6578, PCH. ecc in hole. Picked up top of fish 6578, 5ts. & 27 piece of ge ring to 6530. Ran H w/1-1/2" tbg. w/Baker
circ. out 1200° drlg. mud, sand & shale. Circ. 1-1/2 hrs. on to Recovered 204 jts & 4° piece (total 6578°); left 2 jts. & 27° pi 3" Bowen jars w/overshot, WIH w/rented string of 2" tbg., caught Jarred on fish 1-1/2 hrs. Jarred fish loose, PCH. Recovered 2 1-1/2" tbg. WIH w/3-7/2" bit on 2" tbg.  4/4/68 CC to 6684°. Circ. 2-1/2 hrs. PCH. L.D. 2" tbg, Welex ran gau Baker Model "D" production packer on wire line, set © 6474°. WI Model "D" locator assembly on bottom w/5° of tail pipe. Reverse mixed w/Kem-Pac chemicals, flushed tbg. w/16 bbls of lease oil.	mud. Ran in 20 stands p of fish 3 6578, PCH. ece in hole. Picked up top of fish 6578. 3ts. & 27 piece of ge ring to 6530. Ran H w/1-1/2" tbg. w/Baker d in 125 bbls of oil Set tbg. into Model "D"
circ. out 1200° drlg. mud, sand & shale. Circ. 1-1/2 hrs. on to Recovered 204 jts & 4° piece (total 6578°); left 2 jts. & 27° pi 3" Bowen jars w/overshot, WIH w/rented string of 2" tbg., caught Jarred on fish 1-1/2 hrs. Jarred fish loose, PCH. Recovered 2 1-1/2" tbg. WIH w/3-7/2" bit on 2" tbg.  4/4/68 CC to 6684°. Circ. 2-1/2 hrs. PCH. L.D. 2" tbg, Welex ran gau Baker Model "D" production packer on wire line, set 6474°. WI Model "D" locator assembly on bottom w/5° of tail pipe. Reverse mixed w/Kem-Pac chemicals, flushed tbg. w/16 bbls of lease oil. packer, set 6000% on packer, 10,000% on donut. Squeezed away 3	mud. Ran in 20 stands p of fish 3 6578, PCH. ece in hole. Picked up top of fish 6578. 3ts. & 27 piece of ge ring to 6530. Ran H w/1-1/2" tbg. w/Baker d in 125 bbls of oil Set tbg. into Model "D" nore bbls down annulus.
circ. out 1200° drlg. mud, sand & shale. Circ. 1-1/2 hrs. on to Recovered 204 jts & 4° piece (total 6578°); left 2 jts. & 27° pi 3" Bowen jars w/overshot, WIH w/rented string of 2" tbg., caught Jarred on fish 1-1/2 hrs. Jarred fish loose, POH. Recovered 2 1-1/2" tbg. WIH w/3-7/2" bit on 2" tbg.  4/4/68 OD to 6684°. Circ. 2-1/2 hrs. POH. L.D. 2" tbg, Welex ran gau Baker Model "D" production packer on wire line, set 0 6474°. WI Model "D" locator assembly on bottom w/5° of tail pipe. Reverse mixed w/Kem-Pac chemicals, flushed tbg. w/16 bbls of lease oil. packer, set 6000% on packer, 10,000% on donut. Squeezed away 3 Pressured up to 800%, rigged down blow out preventor. Rigged up	mud. Ran in 20 stands p of fish 3 6578, PCH. ece in hole. Picked up top of fish 6578. 3ts. & 27 piece of ge ring to 6530. Ran H w/1-1/2" tbg. w/Baker d in 125 bbls of oil Set tbg. into Model "D" more bbls down annulus.
circ. out 1200° drlg. mud, sand & shale. Circ. 1-1/2 hrs. on to Recovered 204 jts & 4° piece (total 6578°); left 2 jts. & 27° pi 3" Bowen jars w/overshot, WIH w/rented string of 2" tbg., caught Jarred on fish 1-1/2 hrs. Jarred fish loose, PCH. Recovered 2 1-1/2" tbg. WIH w/3-7/2" bit on 2" tbg.  4/4/68 CO to 6684°. Circ. 2-1/2 hrs. PCH. L.D. 2" tbg, Welex ran gaus Baker Model "D" production packer on wire line, set 9 6474°. WI Model "D" locator assembly on bottom w/5° of tail pipe. Reverse mixed w/kem-Pac chemicals, flushed tbg. w/16 bbls of lease oil. packer, set 6000% on packer, 10,000% on donut. Squeezed away 3 Pressured up to 800%, rigged down blow out preventor. Rigged up Gas TSTM.	mud. Ran in 20 stands p of fish 3 6578, PCH. ece in hole. Picked up top of fish 6578. 3ts. & 27 piece of ge ring to 6530. Ran H w/1-1/2" tbg. w/Baker d in 125 bbls of oil Set tbg. into Model "D" more bbls down annulus.
circ. out 1200° drlg. mud, sand & shale. Circ. 1-1/2 hrs. on to Recovered 204 jts & 4° piece (total 6578°); left 2 jts. & 27° pi 3" Bowen jars w/overshot, WIH w/rented string of 2" tbg., caught Jarred on fish 1-1/2 hrs. Jarred fish loose, POH. Recovered 2 1-1/2" tbg. WIH w/3-7/2" bit on 2" tbg.  4/4/68 OD to 6684°. Circ. 2-1/2 hrs. POH. L.D. 2" tbg, Welex ran gau Baker Model "D" production packer on wire line, set 0 6474°. WI Model "D" locator assembly on bottom w/5° of tail pipe. Reverse mixed w/Kem-Pac chemicals, flushed tbg. w/16 bbls of lease oil. packer, set 6000% on packer, 10,000% on donut. Squeezed away 3 Pressured up to 800%, rigged down blow out preventor. Rigged up	mud. Ran in 20 stands p of fish 3 6578, PCH. ece in hole. Picked up top of fish 6578. 3ts. & 27 piece of ge ring to 6530. Ran H w/1-1/2" tbg. w/Baker d in 125 bbls of oil Set tbg. into Model "D" more bbls down annulus.
circ. out 1200° drlg. mud, sand & shale. Circ. 1-1/2 hrs. on to Recovered 204 jts & 4° piece (total 6578°); left 2 jts. & 27° pi 3" Bowen jars w/overshot, WIH w/rented string of 2" tbg., caught Jarred on fish 1-1/2 hrs. Jarred fish loose, POH. Recovered 2 1-1/2" tbg. WIH w/3-7/6" bit on 2" tbg.  4/4/68 © to 6684°. Circ. 2-1/2 hrs. POH. L.D. 2" tbg, Welex ran gauge Baker Model "D" production packer on wire line, set 66474°. WI Model "D" locator assembly on bottom w/5° of tail pipe. Reverse mixed w/kem-Pac chemicals, flushed tbg. w/16 bbls of lease oil. packer, set 6000% on packer, 10,000% on donut. Squeezed away 3 Pressured up to 800%, rigged down blow out preventor. Rigged up Gas TST  Released rig 8 A.M. 4-5-68  18.1 hereby certify that the information above is true and complete to the best of my knowledge and belief.	mud. Ran in 20 stands p of fish 3 6578, PCH. ece in hole. Picked up top of fish 6578. 3ts. & 27 piece of ge ring to 6530. Ran H w/1-1/2" tbg. w/Baker d in 125 bbls of oil Set tbg. into Model "D" more bbls down annulus.
circ. out 1200° drlg. mud, sand & shale. Circ. 1-1/2 hrs. on to Recovered 204 jts & 4° piece (total 6578°); left 2 jts. & 27° pi 3" Bowen jars w/overshot, WIH w/rented string of 2" tbg., caught Jarred on fish 1-1/2 hrs. Jarred fish loose, PCH. Recovered 2 1-1/2" tbg. WIH w/3-7/2" bit on 2" tbg.  4/4/68 CC to 6684°. Circ. 2-1/2 hrs. PCH. L.D. 2" tbg, Welex ran gau Baker Model "D" production packer on wire line, set © 6474°. WI Model "D" locator assembly on bottom w/5° of tail pipe. Reverse mixed w/Kem-Pac chemicals, flushed tbg. w/16 bbls of lease oil. packer, set 6000% on packer, 10,000% on donut. Squeezed away 3 Pressured up to 800%, rigged down blow out preventor. Rigged up Gas TOTM.  Released rig. 8 A.M. 4-5-68	mud. Ran in 20 stands p of fish 3 6578, PCH. ece in hole. Picked up top of fish 6578. 3ts. & 27 piece of ge ring to 6530. Ran H w/1-1/2" tbg. w/Baker d in 125 bbls of oil Set tbg. into Model "D" more bbls down annulus.
circ. out 1200° drlg. mud, sand & shale. Circ. 1-1/2 hrs. on to Recovered 204 jts & 4° piece (total 6578°); left 2 jts. & 27° pi 3" Bowen jars w/overshot, WIH w/rented string of 2" tbg., caught Jarred on fish 1-1/2 hrs. Jarred fish loose, PCH. Recovered 2 1-1/2" tbg. WIH w/3-7/2" bit on 2" tbg.  4/4/68 CD to 6684°. Circ. 2-1/2 hrs. POH. L.D. 2" tbg, Welex ran gauge Baker Model "D" production packer on wire line, set 66474°. WI Model "D" locator assembly on bottom w/5° of tail pipe. Reverse mixed w/Kem-Pac chemicals, flushed tbg. w/16 bbls of lease oil. packer, set 6000% on packer, 10,000% on donut. Squeezed away 3 Pressured up to 800%, rigged down blow out preventor. Rigged up Gas TOTM.  Released rig 8 A.M. 4-5-68  18.1 hereby certify that the information above is true and complete to the best of my knowledge and belief.  Priginal signed by:  SIGNED SUPPLIFY Superintendent	mud. Ran in 20 stands p of fish 3 6578*, PCH. ece in hole. Picked up top of fish 6578*. gts. & 27* piece of ge ring to 6530*. Ran H w/1-1/2" tbg. w/Baker d in 125 bbls of oil Set tbg. into Model "D" nore bbls down annulus. to swab; swabbed 8 hrs.
circ. out 1200° drlg. mud, sand & shale. Circ. 1-1/2 hrs. on to Recovered 204 jts & 4° piece (total 6578°); left 2 jts. & 27° pi 3" Bowen jars w/overshot, WIH w/rented string of 2" tbg., caught Jarred on fish 1-1/2 hrs. Jarred fish loose, PCH. Recovered 2 1-1/2" tbg. WIH w/3-7/6" bit on 2" tbg.  4/4/68 © to 6684°. Circ. 2-1/2 hrs. PCH. L.D. 2" tbg, Welex ran gau Baker Model "D" production packer on wire line, set © 6474°. WI Model "D" locator assembly on bottom w/5° of tail pipe. Reverse mixed w/Kem-Pac chemicals, flushed tbg. w/16 bbls of lease oil. packer, set 6000% on packer, 10,000% on donut. Squeezed away 3 Pressured up to 800%, rigged down blow out preventor. Rigged up Gas TOTM.  Released rig 8 A.M. 4-5-68  18.1 hereby certify that the information above is true and complete to the best of my knowledge and belief.  Priginal signed by:	mud. Ran in 20 stands p of fish 3 6578*, PCH. ece in hole. Picked up top of fish 6578*. gts. & 27* piece of ge ring to 6530*. Ran H w/1-1/2" tbg. w/Baker d in 125 bbls of oil Set tbg. into Model "D" nore bbls down annulus. to swab; swabbed 8 hrs.
circ. out 1200° drlg. mud, sand & shale. Circ. 1-1/2 hrs. on to Recovered 204 jts & 4° piece (total 6578°); left 2 jts. & 27° pi 3" Bowen jars w/overshot, WIH w/rented string of 2" tbg., caught Jarred on fish 1-1/2 hrs. Jarred fish loose, PCH. Recovered 2 1-1/2" tbg. WIH w/3-7/2" bit on 2" tbg.  4/4/68 CD to 6684°. Circ. 2-1/2 hrs. POH. L.D. 2" tbg, Welex ran gauge Baker Model "D" production packer on wire line, set 66474°. WI Model "D" locator assembly on bottom w/5° of tail pipe. Reverse mixed w/Kem-Pac chemicals, flushed tbg. w/16 bbls of lease oil. packer, set 6000% on packer, 10,000% on donut. Squeezed away 3 Pressured up to 800%, rigged down blow out preventor. Rigged up Gas TOTM.  Released rig 8 A.M. 4-5-68  18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.  Priginal signed by:  SIGNED Superintendent	mud. Ran in 20 stands p of fish 3 6578*, PCH. ece in hole. Picked up top of fish 6578*. gts. & 27* piece of ge ring to 6530*. Ran H w/1-1/2" tbg. w/Baker d in 125 bbls of oil Set tbg. into Model "D" nore bbls down annulus. to swab; swabbed 8 hrs.
circ. out 1200° drlg. mud, sand & shale. Circ. 1-1/2 hrs. on to Recovered 204 jts & 4° piece (total 6578°); left 2 jts. & 27° pi 3" Bowen jars w/overshot, WIH w/rented string of 2" tbg., caught Jarred on fish 1-1/2 hrs. Jarred fish loose, PCH. Recovered 2 1-1/2" tbg. WIH w/3-7/2" bit on 2" tbg.  4/4/68 CC to 6684°. Circ. 2-1/2 hrs. PCH. L.D. 2" tbg, Welex ran gau Baker Model "D" production packer on wire line, set 0 6474°. WI Model "D" locator assembly on bottom w/5° of tail pipe. Reverse mixed w/Kem-Pac chemicals, flushed tbg. w/16 bbls of lease oil. packer, set 0000% on packer, 10,000% on donut. Squeezed away 3 Pressured up to 800%, rigged down blow out preventor. Rigged up Gas TOTE.  Released rig 8 A.M. 4-5-68  18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.  Priginal signed by:  SIGNED SUPERVISOR DIST. #5	mud. Ran in 20 stands p of fish 3 6578*, PCH. ece in hole. Picked up top of fish 6578*. gts. & 27* piece of ge ring to 6530*. Ran H w/1-1/2" tbg. w/Baker d in 125 bbls of cil Set tbg. into Model "D" nore bbls down annulus. to swab; swabbed 8 hrs.

•

 $\int$