## (SUBMIT IN TRIPLICATE)

## UNITED STATES DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY

Budge Appro	Bureau No. 42-R358.4. val expires 12-31-60.
Land Office	Santa Po
Lease No.	75089
GC V <sup>4</sup>	t Scott

GPO 918507

Unit .....

NOTICE OF INTENTION TO CHANGE PLANS	li li	•		
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.		SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING		
	SUBSEQUENT REPORT OF ALTERING CASING. SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR			
IOTICE OF INTENTION TO CHOOT OF ACIDITE				
MOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF			
NOTICE OF INTENTION TO PULL OR ALTER CASING.	SUPPLEMENTARY WELL H			
NOTICE OF INTENTION TO ABANDON WELL.	Surrace Casing		3CK	
(INDICATE ABOVE BY CHECK MARK NA	ATURE OF REPORT, NOTICE, OF	OTHER DATA)		
-	September 25 , 19 59			
ell No. scott 38 is located 990 ft. from	N line and 1650	ft. from   ine of s	ec. <b>2</b> 2	
NW NE Sec. 22 27 N	11 W New M	zico PM	11/1	
Sent Jutz - Plotured Cliffs San Ju		How float HUL	IVEC	
(Field) (County or S	Subdivision)	(Stage of Territary)		
<del></del>	er important proposed work;	-	-	
rilled 13-3/4" hole to 335' AB. San asing equipped with Entional Texas problemation slip weld by Srd collar - 4th 275 sx. of consut with 2% calcius ith good returns to surface. Saited asing to 700 pei for 30 min. Held Ch	etter slip weld : 320°. Landed at a chloride. Mag 24 hours on cem	shoe and National 5 333' KB and com placed coment to ;	exted 318' KB	
		ev before operations may be c		
I understand that this plan of work must receive approval in w		by second operations may be c	ommenced.	
The Reitish-American Cil Proc			ommenced.	
	ducing Company			
ompany The British-American C11 Proc	ducing Company	Original Samed I		