

F. Loc. 1450/S; 790/W Elev. 6186 DF Spd. 5-15-52 Comp. 6-16-52 TD 2156 PB

Casing S. 8-5/8 @ 129 W. 60 Sx. Int. @ W. Sx. Pr. 5 1/2 @ 2093 W. 100 Sx. T. 1 @ 2129
Csg. Perf. Prod. Stim.

TRANS
ECL

I.P. 857 ~~80/D~~ MCF/D After 3 Hrs. SICP 605 PSI After 8 Days GOR Grav. 12-15-53 s INC

TOPS		NITD	Well Log	TEST				DATA			Ref. No.
Kirtland		C-102	Plat	Schd.	PC	Q	PW	PD	D		
Fruitland		C-103	Electric Log	<u>4/18/66</u>	<u>373</u>	<u>113</u>	<u>111</u>	<u>298</u>	<u>52</u>		
Pictured Cliffs	<u>2090</u>	C-104	C-110	<u>1/18/67</u>	<u>388</u>	<u>123</u>	<u>165</u>	<u>310</u>	<u>61</u>		
Cliff House			C-122								
Menefee		Ditr	Dfa	<u>8/18/69</u>	<u>380</u>	<u>42</u>	<u>208</u>	<u>304</u>	<u>24</u>		
Point Lookout		Datr	Dac	<u>7/15/70</u>	<u>292</u>	<u>27</u>	<u>213</u>	<u>234</u>	<u>22</u>		
Mancos		Remarks		<u>9/18/72</u>	<u>341</u>	<u>38</u>	<u>182</u>	<u>273</u>	<u>21</u>		
Gallup				<u>5/18/73</u>	<u>369</u>	<u>50</u>	<u>175</u>	<u>295</u>	<u>26</u>		
Sanostee				<u>5/3/75</u>	<u>334</u>	<u>42</u>	<u>153</u>	<u>267</u>	<u>22</u>		
Greenhorn				<u>7/3/77</u>	<u>267</u>	<u>24</u>	<u>178</u>	<u>214</u>	<u>17</u>		
Dakota				<u>5/2/79</u>	<u>275</u>	<u>24</u>	<u>150</u>	<u>220</u>	<u>14</u>		
Morrison				<u>8/24/81</u>	<u>303</u>	<u>28</u>	<u>153</u>	<u>242</u>	<u>18</u>		
Entrada				<u>9/21/83</u>	<u>311</u>	<u>23</u>	<u>249</u>	<u>249</u>	<u>23</u>		
PCD	<u>4096</u>			<u>12/1/55</u>	<u>225</u>						

(1.00)
161.58

P
o
o
I. Ful-Kutz PC Co. S.J.s 7 T. 27N R. 9W U.L. Oper. Southland Royalty Co Lse. Hanks No. 5

