

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPPLICATE
(Other instructions on re-
verse side)

Form approved.
Budget Bureau No. 1004-0135
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different depth.
Use "APPLICATION FOR PERMIT" for such proposals.)

1. OIL WELL ☐ GAS WELL ☒ OTHER ☐	7. UNIT AGREEMENT NAME
2. NAME OF OPERATOR Southland Royalty Company	8. FARM OR LEASE NAME Frontier B
3. ADDRESS OF OPERATOR Post Office Box 4289, Farmington, NM 87499	9. WELL NO. 5
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface 660'N, 660'E	10. FIELD AND POOL, OR WILDCAT Kutz Gallup
11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 9, T-27-N, R-11-W	12. COUNTY OR PARISH NM
14. PERMIT NO.	13. STATE
15. ELEVATIONS (Show whether OP, RT, GR, etc.)	

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF

PULL OR ALTER CASING

WATER SHUT-OFF

REPAIRING WELL

FRACURE TREAT

MULTIPLE COMPLETION

FRACURE TREATMENT

ALTERING CASING

SHOOT OR ACIDIZE

ABANDON*

SHOOTING OR ACIDIZING

ABANDONMENT*

REPAIR WELL

CHANGE PLANS

(Other)

(Other)

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

It is intended to plug and abandon this well in the following manner:

MOL&RU. Pull RWBC pump. NU BOP. Release packer @ 5777'. TOOH & lay down. Set cement retainer @ 5900' and squeeze 27 sx (31.6 cu.ft.) Cl B cmt. into Gallup perms. Spot 55 sx (64 cu.ft.) on top of retainer to 5450'. Perforate squeeze holes @ 3630'. Set cement retainer @ 3580' and squeeze 22 sx (25.7 cu.ft.) Cl B across Cliff House. Spot 6 sx (7 cu.ft.) 50' on top of retainer. Displace hole with 9.2# gel mud. Spot 100' cement plug across Chacra. Displace hole with 9.2# gel mud. Spot 31 sx (36.2 cu.ft.) Cl B cement 2060 to 1750' to cover Pictured Cliffs and Fruitland. Displace hole w/9.2# gel mud. Perforate 2 squeeze holes @ 1040. Set retainer @ 890' and squeeze 49 sx (57. cu.ft.) across Kirtland and Ojo Alamo to 840'. Spot 50' cement on top of retainer. Displace hole w/9.2# gel mud. Perforate two squeeze holes @ 220' (50' below surface casing). Circ. 90 sx (105 cu.ft.) Cl B cement to surface. Cut off wellhead and set P&A marker.

18. I hereby certify that the foregoing is true and correct

SIGNED Peggy Doak

TITLE Drilling Clerk

DATE 12-22-87

(This space for Federal or State office use)

APPROVED BY _____
CONDITIONS OF APPROVAL, IF ANY:

TITLE _____

*See Instructions on Reverse Side

NM000