

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease
State Fee

5. State Oil & Gas Lease No.
E-1200

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

OIL WELL GAS WELL OTHER

Name of Operator
DUGAN PRODUCTION CORP.

7. Unit Agreement Name

8. Farm or Lease Name
Farming D Com

Address of Operator
P O Box 208, Farmington, NM 87401

9. Well No.
1

Location of well
UNIT LETTER M 845 FEET FROM THE South LINE AND 790 FEET FROM

10. Field and Pool, or Wildcat
So. Blanco P.C.

West THE LINE, SECTION 2 TOWNSHIP 27N RANGE 9W NMPM.

15. Elevation (Show whether DF, RT, GR, etc.)
6232' D.F.

12. County
San Juan

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK

TEMPORARILY ABANDON

PULL OR ALTER CASING

OTHER

PLUG AND ABANDON

CHANGE PLANS

OTHER

SUBSEQUENT REPORT OF:

REMEDIAL WORK

COMMENCE DRILLING OPNS.

CASING TEST AND CEMENT JOB

OTHER

ALTERING CASING

PLUG AND ABANDONMENT

OTHER

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Plan to plug and abandon well as follows:

1. Spot cement plug 2371-2260'.
2. Spot cement plug 2080-1980'.
3. Find free point and shoot off casing.
4. Spot 100' cement plug at casing stub.
5. Spot 100' cement plug at 1240-1140'.
6. Spot 100' plug 210-110'.
7. Spot 10 sk cement plug at surface.
8. Install dry hole marker and clean up location.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Jim L. Jacobs TITLE Geologist DATE 8-10-82

APPROVED BY Jeff Edmister TITLE DEPUTY OIL & GAS INSPECTOR, DIST. #3 DATE AL

CONDITIONS OF APPROVAL, IF ANY: