

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Form Approved
Budget Bureau No. 42-R1424

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different interval. Use Form 9-331-C for such proposals.)

1. ON ☒ WELL ☐ GAS ☐ OIL ☐ OTHER ☐
2. NAME OF OPERATOR
El Paso Natural Gas Company
3. ADDRESS OF OPERATOR
P. O. Box 289, Farmington, N. M. 87401
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)
AT SURFACE: 1450'S, 1800'E
AT TOP PROD. INTERVAL:
AT TOTAL DEPTH:
15. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL FOR:

TEST WATER SHUT-OFF ☐

FRACTURE TREAT ☐

SHOOT OR ACIDIZE ☐

REPAIR WELL ☐

PULL OR ALTER CASING ☐

MULTIPLE COMPLETE ☐

CHANGE ZONES ☐

ABANDON ☐

(other) ☐

SUBSEQUENT REPORT OF:

5. LEASE

SF 078050

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Turner Hughes

9. WELL NO.

9

10. FIELD OR WILDCAT NAME

So. Blanco Pictured Cliffs

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

Sec. 4, T27N, R9W

12. COUNTY OR PARISH 13. STATE

San Juan New Mexico

14. API NO.

15. ELEVATIONS (SHOW DF, KDB, AND WD)

6406' DF

(NOTE: Report results of multiple completion or zone change on Form 9-332.)

GEOLOGICAL

ENGINEERING

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

1. Kill and circulate the well and pull the 1" tubing.
2. Run a work string and spot a bottom plug to fill the open hole plus 50' of the 5 1/2" casing.
3. Perforate the 5 1/2" casing at 1640' and squeeze cement to 1445'.
4. Spot a plug inside the 5 1/2" casing from 1640' to 1445'.
5. Perforate the 5 1/2" casing at 152' and squeeze cement to surface in the 5 1/2-5 3/8" annular space.
6. Spot a plug inside the 5 1/2" casing to surface and install a dry hole marker. (50' plug)
7. Remove surface equipment and restore surface.

Subsurface Safety Valve: Manul. and Type

Set @ _____ Ft.

18. I hereby certify that the foregoing is true and correct

SIGNED Raymond W. Vinyard TITLE Engineer DATE 10-27-81

(This space for Federal or State office use)

APPROVED BY (Orig. Sgd.) RAYMOND W. VINYARD TITLE ACTING DISTRICT SUPERVISOR DATE NOV 03 1981
CONDITIONS OF APPROVAL, IF ANY

