(SUBMIT IN TRIPLICATE)

UNITED STATES DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY

Land (Office -	Sente	<u> 7e </u>	
Lease	No	070935	5	

Unit 5% /1 Sec. 3 7278, 112%

SUNDRY I	NOTICES AN	D REPORTS	ON WELL	S OIL COM. COM.
NOTICE OF INTENTION TO DRILL	ANSR SHUT-OFFR REPAIR WELLACIDIZETER CASING	SUBSEQUENT REPORT OF SUBSEQUENT REPORT OF SUPPLEMENTARY WELL	SHOOTING OR ACIDIZING ALTERING CASING	R
(INDICATE	ABOVE BY CHECK MARK NAT	TURE OF REPORT, NOTICE, C	OR OTHER DATA)	
	•	Ju	ily 27	, 19.52
Well No. 3. Thompson is loca			ft. from $\left\{ egin{array}{c} \mathbf{E} \\ \mathbf{W} \end{array} \right\}$ line	e of sec3
SE/4 Sec. 3 (14 Sec. and Sec. No.)	7-274, 1-124	Panga) (A	Meridian)	
(M Sec. and Sec. No.)		<u> </u>		itory)

The elevation of the derrick floor above sea level is 5008... ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Well was souded July 17, 1751. 90' of 8-5/8" casing was described with 30 sacks. On July 18th, prior to irilling plug, easing tested 500% for 30 minutes with no drop in pressure. Plug was drilled and Thid level was checked for 30 minutes with 500% with no drop.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.						
Company Danube Oil Company						
Address 213 First Mational Bank Smilding						
Amerillo, Teres	By By					
	Title Acens					
U. S. GOVERNMENT PRINTING OFFICE	16-8437-4					