Form 9-331 Dec. 1973

Form Approved.

Budget Bureau No. 42-R1424

UNITED STATES	5. LEASE
DEPARTMENT OF THE INTERIOR	SF078895
GEOLOGICAL SURVEY	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
	ACRESIANT NAME
SUNDRY NOTICES AND REPORTS ON WELLS	7. UNIT AGREEMENT NAME
Do not use this form for proposals to drill or to deepen or plug back to a different eservoir. Use Form 9–331—C for such proposals.)	8. FARM OR LEASE NAME
	Mudge "A"
1. oil gas well other	9. WELL NO.
2. NAME OF OPERATOR	5
DEPCO, Inc.	10. FIELD OR WILDCAT NAME
3. ADDRESS OF OPERATOR	W. Kutz P.C: 11. SEC., T., R., M., OR BLK. AND SURVEY OR
1000 Petroleum Building - Denver CO 80202 4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17	AREA
to the same	Sec. 6-T27N-R11W
AT SURFACE: 1650' FSL, 990' FEL (NE/4 SE/4)	12. COUNTY OR PARISH 13. STATE
AT TOP PROD. INTERVAL: Same AT TOTAL DEPTH: Same	San Juan NM
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE,	14. API NO.
REPORT, OR OTHER DATA	15. ELEVATIONS (SHOW DF, KDB, AND WD)
To the second se	-6067' IGR 3
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF:	
FRACTURE TREAT	an - → ★製造 原 (1994年)
SHOOT OR ACIDIZE	
REPAIR WELL	(NOTE: Report results of multiple completion or zone change on Form 9–330.)
PULL OR ALTER CASING U.S. DU.S. DU.S	
CHANGE ZONES	
ABANDON* (other) Request for Continuation of Current SI Sta	tus Santa
17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly statincluding estimated date of starting any proposed work. If well is a measured and true vertical depths for all markers and zones pertine	illectionally diffied, give substitute to the area
It is requested that a continuation of the	current shut-in status for
the subject well be granted for the following r	easons:
1. The well is located upon cultivated la	nd under center-pivot
irrigation operated by NAPI. Any reme	dial work to be done
would necessarily have to be performed	during the non-growing
season.	발표한 사람들은 사람들이 되었다.
2. The value of a replacement well is unc	ertain because 18 Pic-
tured Cliffs wells completed in this T	ownship by DEPCO, Inc.
nine months ago remain unconnected due	to gathering time
right-of-way problems confronting the	gas purchaser. Wo of PLA
ork by november 1, 1982. Sundy Thote	
Subsurface Safety Valve: Manu. and Type	Set @Ft
18. I hereby certify that the foregoing is true and correct	
1 WALL STATE OF THE PROOF COUNTY	So. DATE April 21, 1982
ADDDOVED	Rockies
APPROVED This space for Federal or State of	
APPROVED BY TOUR HOLDEN	
CONDITIONS OF APPRIPAR. & 9N 1982	MAY 3 1982
AS AMENDED FOR JAMES F. SIMS	OIL CON. COM.
DISTRICT ENGINEER	DIST. 3
I	