



It is of the greatest importance to have a complete history of the well. Please state in detail the dates of redrilling, together with the reasons for the work and its results. If there were any changes made in the casing, state fully, and if any casing was "sidedrilled," or left in the well, give its size and location. If the well has been dynamited, give date, position, and number of shots. If plugs or bridges were put in to test for water, state kind of material used, position, and results of pumping or bailing.

11-28-57 Tested for leak w/Fulbore. Found leak between 2322 & 2352. No. same w/100 sks. Neat cement. Held 20607.

I.D. 4771. 0.125. 474. Placed Joint Lookout pert. Int. 470-471, 4533-4572, 4596-4608, 4627-4646, 4658-4682, 4708-4716 (2 SPS) w/73,000 gal. water & 60,000 sand. BIV-More. Max. tr. 2400#, ave. tr. nr. 3100-2300-2200-2700. I.R. 64 B.M. Flush 7600 gal. water. Injected 3 sets balls (5) balls. Set. Set pump, br. line 24251. Placed 4ctured 11155 pert. Int. 2262-2280, 2288-2314 (2 SPS) w/33,200 gal. water and 40,000 sand. BIV 2100#, Int. tr. 2500#, ave. tr. 1750-2100#. I.R. 67 B.M. Flush 4700 gal. water. Injected 1 set of 30 balls.