Form 3160-5 (June 1990)

## **DEPAR** BUREAU OF LAND MANAGEME

UNITED STATES	FORM AF
TMENT OF THE INTERIOR	Budget Bureau Expires: Mai
LOF LAND MANAGEMENT	Expres. Iviai

FORM APPROVED					
Budget Bureau No. 1004-0135					
Expires: March 31, 1993					

0	TIOTO AND DEDODE	0.011.1451		5. Lease Designation and Serial	No.
SUNDRY NOTICES AND REPORTS ON WELLS			/ NM-012200		
Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.			6. If Indian, Allottee or Tribe Name		
Use "APPLIC	CATION FOR PERMIT - " for su	cn proposals			
				7. If Unit or CA, Agreement D	esignation
	٠. ٠	er • e r			
. Type of Well				-	
Oil Ges Well Other				8. Well Name and No.	
2. Name of Operator Attention:			Dryden LS #3		
Amoco Production Company				9. API Well No.	
3. Address and Telephone No.			30045	3004507244	
P.O. Box 800, Denver, Colorado 80201 (303) 830-6157		10. Field and Pool, or Explorat	10. Field and Pool, or Exploratory Area		
4. Location of Well (Footage, Sec., T., R., M., o	r Survey Description)			Blanco So (PC)/Bl	anco Mesaverde
990FSL 990FWL	Sec. 21 T 2	8N B 8N/	Unit M	11. County or Parish, State	
990F3L 990FWL	. Sec. 21 1 20	014 11 044	Offic IVI	San Juan	New Mexico
0115014 4 555 055	LATE DOWN TO INDIC	ATE NATUR	F OF MOTICE !	!	DATA
	IATE BOX(s) TO INDICA	ATE NATUR		REPORT, ON OTHER	DATA
TYPE OF SUBMISSION			TYPE OF ACTION	·	· · · · · · · · · · · · · · · · · · ·
		bandonment		Change of Plans	
Notice of Intent		ecompletion	-	New Construction	•
E-20		ugging Back		Non-Routine Fracturing	
Subsequent Report	· ·   c₁	asing Repair	<u></u>	Water Shut-Off	
		Itering Casing ther Bradenhead	Renair	Conversion to Injection	
Final Abandonment Notice	<b>△</b> 01	ther <u>Braderineau</u>	_	」 Dispose Water port results of multiple completion ∈	on Well Completion or
				tion Report and Log form. )	
Amoco Production Compan  If you have any technical qu the telephone number listed	estions please contact Lara F		3) 830-5708 or my		
14. I hereby certify that the foregoing is true and Signed  (This space for Federal or State office use)  Approved by Conditions of approval, if any:	Heism	Title _	Business As	JOEPTED FOR	03-21-1995 RECORD
~				MAR 2 3 19	95
Title 18 U.S.C. Section 1001, makes it a crime representations as to any matter within its jurisd		ake to any departmen	t or agency of the United St	ates any false, ficticious, or fraudul	
oprovented one as to entrinsect tricine its jurisc				FARMINGTON DISTI	KICH OFFICE

Bradenhead Repair --

Dryden LS #3

Arrive Location, RUSU & Spot Equip - 1/28/95

P.C. Csg. Press - 135#, P.C. Tbg Press - 135#, M.V. Tbg - 300#, RU flowlines and blew down pres. NDWH & NUBOP's, TOH w /1 1/4" linepipe w/holes drilled in the last 20 jts. RU 2.375" tbg equip & tried to pull donut and donut would not come thru BOP's. SDFN.

SDF mud.TOH w/pkr & TIH w/tbg & spot sand on 5.5" plg. TOH w/tbg & TIH w/7 5/8" plug & set plg @ 1975'. Loaded csg w/wtr & tst'd csg to 1000#. Csg held. Press. for 15 min. TOH w/tbg and dumped sand on plg. SDFN.

MIRU HES & ran CBL/CCL/GR from 1400' to surface-TOC = 770'. TIH w/squeeze guns and shot holes @ 270' & 271 (1 jspf). RD HES and Pumped into holes and Cir B. Head. MIRU HES & cmt'd well to surface 35 bbls cmt, pumped 8 bbls cmt to pit 10 bbls wtr. Good Circ all thru job. SDFN.

P.U. Drill CCLS, bit & scraper and TIH w/tbg & tagged cmt @ 202'. Drilled out cmt t0 260' & cmt turned softer. Drilled out of cmt @ 281' and circ hole clean. SDF day.

RU Pump & press tst'd csg to 500# & csg bled off to 300# in 1 min & 0# in 4 min. pressured well to 700# & well broke dn. Pumped into squeeze @ 2 BPM @ 600#. RU HES cmt & pumped 125 sx cmt w/final press of 230#. RD cmt & SWI. BH press = 8#.

TIH w/bit, scraper & ccls & tag cmt @ 196' and drilled out of cmt @ 326'. Cir hole clean. Pres tst'd squeeze to 500# and squeeze held press. TIH w/tbg to 1970' & circ hole clean. TOH w/tbg & laid down CCLS. TIH w/ret head & RU Air & Cir sand off plug & TOH w/plug. SDFN.

Csg press - 165#, blew dn press & TIH w/ret head. RU Air comp & circ sand off 5.5" RBP & released Plg. Blew dn press & TOH w/RBP & TIH w/Sawtooth CCL & Tbg & C\O fill to 4602'. w/air. C\O Rig pit & TOH w/tbg & SDFN.

CSg press - 350#, blew dn press & TIH w/prod tbg & tried to set pkr & pkr would not set. TOH w/pkr & change out pkr to HAL Perm Lok Set pkr & TIH w/muleshole, 1 Jt, X-Nipple, 65 jts, perm lock set pkr, & 77 jts tbg. Set pkr @2451' w/ K.B> Bot of Tbg @ 4544'.

X-Nipple @4512'. Change out equip for 1 1/4" equip & TIH w/orange peel perf'd jt. 106 jts 1 1/4" tbg. Landed tbg @ 2251' w/K.B. NDBOP & NUWH. RU air & pumped out plg in long string. Press tst'd wellhead pkg to 1100# & held. PU Equip & SDFN. RDMOSU 3/16/95